LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Wexford	Locate	ed In	Corner Code #		
(County)					
1. Public Land Survey	T 23N T 23N	R 10W R 9W	MS 		
Property Controlling in Section	s T	R			
Miscellaneous Property in Section	S T S T	R R		Register of Deeds Stan	np & File Number
4. Lot No:	Recorded Plat:			ABCDEFGH	ı j K L M
5. Private Claims:				1 2 6 5 4 3	
I, Craig W. McVean, in a field survey on Oct. 25, 2007 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.					
A. Description of original monument and accessories and/or subsequent restoration:					
A6 & M6 – 1838 – GLO ¼ Section post by John Brink, Deputy Surveyor, 1) Sugar 14" S2°W 54; 2) Sugar 13" N43°W 13 - 1985 – Wade-Trim/Granger LCRC, Liber 03, page 333, set ½" iron in centerline road opposite old fence line West; 3) N51°E 24" Apple 48.00'; 4) N32°W 14" stump 37.52'; 5) S9°W 18" Maple 105.80' - 1994 – LCRC – L. 4, p. 273 – G. D. Smith - Found Wexford County monument (good condition) in centerline roads North-South and opposite old fence West. This corner is accepted as a careful and faithful reestablishment of the position of the original corner, being the ¼ corner common to Section 13, T23N, R10W and Section 18, T23N, R9W. 3) N51°E – 47.96' – 24" Apple 5) S9°W – 105.72' – 18" Maple 6) S20°W – 129.12' – Power Pole 7) N75°E – 62.92' – 6" Ash B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:					
A6 & M6 — Standard ¼ corner common to Sec. 13, T23N, R9W and Sec. 13, T23N, R10W — Found 4" Wexford County Aluminum Monument in poor condition per LCRC L.4, p. 273. In centerline of N-S Gravel Road. Centerline sand drive East is 6'± South. Excavated monument and found 2 RR spikes and ½" rebar alongside monument. Wexford County Aluminum Monument accepted as the best available evidence of the position of the original corner. Witnesses 1, 2, 3, & 4 are gone. #5 is dead and to the SE not SW.					
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:					
3" x 8" long F new monume N57°W 59.64 S38°W 56.86 N73°E 62.88 S5°E 135.00	PVC with concrete an ent as memorials. 4' to set Nail & Tag in 8' to set Nail & Tag in 'to set Nail & Tag at 'to set Nail and Tag at 'to set Nail in East 'to fd. nail in East	ound cap – E NE side Tw NW side 10 old nail in N in West side	Down 0.7'. Placed brok in 6" & 4" Red Pine " Red Pine orth side 12" Ash (#7) 14" R. Pine pole (#6)	Wexford County Brass Cap on en up Aluminum Monument & 2	CRAIG W. MCVEAN PROFESSIONAL