RECEIVED

DEC 2 0 1999

WASHTENAW COUNTY ROAD COMMISSION

LAND CORNER RECORDATION CERTIFICATE

RE

٠.,

Z.00H Filing Requirement of Act 74, Mich. P.A. 1970 or Corners in SECTION Corner Code # Located In: Washtenaw Public Land Survey 1 of 1 R 02/07/2000 02:55P R **Property Controlling** - Washtenaw Co. CORREM L-3 P-34 in Section R Miscellaneous R Register of Deeds Stamp & File Number Property in Sec. Recorded Plat Lot No. Private Claim 6 December in a field survey on Timothy Tietsema hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the rent manual of survey instructions of the United States Department of the Interior, Bureau of Land ranagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 Dove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a established, re-established, monumented, re-monumented, recovered, found as ourt of Law: pressed below: 10 -OTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. Description of original monument and accessories and/or subsequent restoration: 6" Hickory 24" Black Oak 10 lks. 1825 J. Wampler Set original corner S20W N30E 81 lks. 2) GLO 6" Hickory 24" Black Oak Date unknown S.B. Pettibone Unknown 1) \$20W 10 lks. Wash, Co. Road Comm. N30E 2) 81 lks 15" Hickory 3) N77E 29 lks. N'ly SW'ly 1960's Washlenaw Eng. Field Found iron pipe 6" Tri-Basswood 10.2 28" R. Oak 13.5 John Oliver Notes in rock pile. 5) SE'ly straightened 12" W. Oak 27.2 6) And reset. E-W Fence North 6' 8) Fence N'ly 41' East SW cor, Fnc. post 08/07/1978 Norman N. Fahrner LCRC Found iron pipe 9) NIOE 1.5276 10) 6" Willow \$75W 9 4' #17620 12" Maple N05F (job #15948) (Erroneous 45.9 5" Willow 50,3 Recordation) West

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of previous monumentation was found in the vicinity of the corner location. The corner location was re-established in a rock pile. using accessories 4,5,6, and 7 above.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/" iron pipe with Washtenaw County Remonumentation Cap in rock pile, with Michigan State Plane Coordinates values of North 306,754,58 and East 13,233,686.58. Accessories perpetuated or established as follows:

4) 14" Dbl-Basswood	N05E	10.201	Set P.K. Nail with Remonumentation Washer on west side
5) 36" Oak	S55W	13,50'	Set P.K. Nail with Remonumentation Washer on north side
6) 18" Oak	S50E	27.20'	Set P.K. Nail with Remonumentation Washer on west side
7) E-W fence line	North	6.0'	
13) 18" Oak	N65E	24.00'	Set P.K. Nail with Remonumentation Washer on South side
15) NW corner	Wiv	293.811	Found 3/" iron pipe

Sec. 3, T2S, R4E

reestablishment of the position of the original corner based upon the best available evidence. I find that this corner represents a This corner ratified by the Wash nmittee on December 6, 1999.

20 December 1999 igned by Date_ ∎urveyor's Michigan License SS/ONAL S