LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

			······································		•
For co	orners in				
Was	htenaw (County)	Located In:	Corner Code #		
1. Pul	olic Land Survey	T_2S_ R_5I T R T R	3 <u>I-12</u> — — 	5094728 Page: 1 of 2 92/07/2000 92	::55P
in 3. Mi Pro	perty Controlling Section scellaneous perty in Section	T R S T R S T R S T R S T R		Haines - Washtenaw Co. CORREM L-2 P-327 Register of Deed Stamp &	
		orded Plat			K L M
I, 7 und me rul Unded and La mo	Thomas L. Sutherland, in the requirements of P.A. Intioned in lines 1 and 2 are therefore as required ited States Department of the following the states of a Court of Law at 15 above were in conform Surveyors or by a Denumented, recovered, for the conformation of the state of the covered of the covered of the covered on this covered on the covered on this covered on this covered on this covered on this covered on the covered on this covered on this covered on this covered on the covered on this covered on the covered on the covered on the covered on the covered on this covered on the co	monument and accessories : Notes E 20 Links	99 do hereby state that 0, the corner points the with regulations and provey instructions of the land Management or by a sementioned in lines 3, 4 to Michigan Board of stablished, re-established, and range, may be	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	12 -
В.	Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
-	Found 3/4" iron pipe 0.19 South of bottom of .7x.6 concret end post (leaning slightly north). Tried to remove pipe but couldn't. Dug down 12" and found pipe to be surrounded by roots and bricks. Set aluminum remonumentation cap stamped 24620 over existing pipe				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:					
	crete end post (leanin 3) 20" Oak (grouped 5) Remains of Apple 6) 14" Oak N32°W 7) 6" Ash S70°E 25 8) 14" Oak S15°E 29		"Elm) N03°E 12.00 to otting) S15°E 14.8 I.E. side side y side	0.19 South of base of .7x.6 con-	
				•	

I conclude after careful study of the record documentation and field observation, that this corner is accepted as the best available evidence of the position of the original corner.

24620

Signed by: Surveyor's Michigan License No. _

No. 24620

MORRADAY

SECTION



A. Continued

W.C.R.C., W.J. Armstrong # 2444, 9/9/38 Grid Book

- 3) 6" SW Oak N3ºE 11.4
- 4) 6" Elm N88ºE 31.5
- 5) 5" Apple S10°E 15.9

R.T. Tietsema #20712, 1/20/75, L.C.R.C., Liber 3, page 595

3/4" Iron pipe at S. end of 6" Square F. Post

- 3) Tri 12-12-8 S. Oak N3ºE 11.53 to Spike
- 5) 14" Apple S10°E 14.62 to Spike
- 6) 8" W. Oak N40°W 13.95 to Spike

Midwestern Consulting, A.R. Rentschler, #15411, 12/28/78, Survey 78441

3/4" Iron pipe on South side of concrete fence post

- 3) 16" Tri Oak N3ºE 11.5
- 5) 14" Apple S10°E 14.7

C. Wilson and Assoc., C. C. Wilson # 13604 7/20/79 Survey 79146

3/4" Iron pipe

- 3) Triple 12-12-8 Oak N3ºE 11.53 to Nail
- 5) 14" Apple S10°E 14.62 to Nail
- 6) 8" W. Oak N40°W 13.95 to Nail

Washtenaw Engineering, N.N. Fahrner #17620, 5/27/81, L.C.R.C., Liber 6, page 150 - T.L. Sutherland # 24620, 6/2/81, Survey R-4735

1" Iron pipe on South side concrete post

- 3) 12" Oak N3ºE 11.4
- 5) 15" Apple S10°E 15.3
- 6) 6" Oak N32°W 13.9

Ayres, Lewis, Norris and May, C.C. Wilson #13604, 9/20/85, Survey 82252-01

- 1" Iron pipe on South side of a concrete post
- 3) 12" Oak N3ºE 11.4
- 5) 15" Apple S10°E 15.3
- 6) 6" Oak N32°W 13.9

Land Surveying Consultants, R.T. Tietsema #20712, 6/92, Survey 06692-2S5E34, 8/96, Survey 09596-2S5E34

3/4" Iron pipe on South side of a concrete post

- 3) Triple 12-12-8 Oak N3ºE 11.53
- 5) 14" Apple S10°E 14.62
- 6) 8" W. Oak N40°W 13.95