2020

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

## CECTION

OCC I ICH							
For corners in	·						
Washtenaw (County)	Located In:	Corner Code #					
1. Public Land Survey	T_2S_ R_5 T R T R T R		aines – Washter	haw Co. CORRI	III	of 2 000 02:5	5P
2. Property Controlling in Section	S T R S		1000				
3. Miscellaneous Property in Section	S T R S T R		100	-Register	r of Deed St	amp & Fi	le Numb
4. Lot No, Recor	ded Plat		A B C	DEF	G H	I J K	LN
5. Private Claims			2 - 6 +	-5 + 4	<u> </u>	2	- 1 -
I, Thomas L. Sutherland, in under requirements of P.A. mentioned in lines 1 and 2 a rules therefore as required in United States Department of decree of a Court of Law an and 5 above were in confort Land Surveyors or by a Dec monumented, recovered, for NOTE: Not more than 2 corecorded on this confort Land Surveyors of the Court of Cou	74, Michigan P.A. of 19 bove were in conformar in the current manual of so the Interior, Bureau of dor that the corner point mance with the rules of the Corner of Law; and as expressed below: orners, all in the same to critificate.	70, the corner points nee with regulations and survey instructions of the Land Management or by a ats mentioned in lines 3, 4 the Michigan Board of established, re-established, wn and range, may be	3 4 - 7 - 5 6 - 18 - 7 8 - 19 - 9 10 - 30 - 11 12 - 31 - 13	- 20 21 - 29 28		23-	- <del> </del> - 25 -

Continued on Back

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 3/4" x 16" gas pipe 8" below Easterly edge of gravel surface above 1/4" x 1 1/2" x 6" iron strap, above iron rod inside and above 1/2" iron pipe 26" below surface surrounded by large rocks and brick fragements. Set 1" x 24" iron pipe with aluminum remonumentation cap stamped 24620 over rod and 1/2" iron pipe 6' below surface. Replaced rocks around new pipe

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" x 24' iron pipe with aluminum remonumentation cap stamped 24620 6" below Easterly edge of gravel surface, over existing iron rod and 1/2' iron pipe surrounded by rocks.

Stub of broken PK nail in chiseled hole of concrete drive apron

- 7) Power pole N85°E 34.39 to remon tage on N. Side
- 8) Power Pole West 39.71 to PK on S. Side
- 9) 18" Oak S40°E 30.92 to remon tag on SW Side
- 10) 30" Oak S40°W 74.83 to remon tag on NW Side
- 11) 36" Oak S35°W 95.41 to remon tag on SE Side
- 14) 30" Oak N30°E 65.25 to remon tag on NW Side
- 15) 12" Walnut N40°W 43.36 to remon tag on SW Side

The second secon	the best available
I conclude after careful study of the record documentation and field observation, that	this corner is accepted as the best available
1 Conclude after careful study of the rooted to the state of the state	
I conclude after careful study of the record documentation and field observation, that evidence of the position of the original corner.	

**JPPHOVED** 

Surveyor's Michigan License No.

## A. Continued

H.H. Atwell #322, No Date, Grid Book

- 3) 14" Elm S54 1/2°W 46.7
- 4) 16" Elm N77°W 28.4
- 5) 6" B. Oak N17 1/2°W 76.4
- 6) 7" W. Oak N14°W 76.4

Washtenaw Engineering, J.F. Oliver #19840, 3/1/74, L.C.R.C. Liber 4, Page 101; 3/1/74, Survey R-3238; N.N. Fahrner #17620, 6/21/76, Survey R-3733;-11/9/77,-----Survey R-4039; 1/9/85, Survey R-5184; 7/2/88, Survey R-5823

3/4" Iron Pipe

3) 30" Elm S54 1/2°W 46.7

- 7) Power Pole N88°E 34.5
- 8) Power Pole West 29.8
- 9) 8" Oak S40°E 31.0

Atwell-Hicks, R.J. Jagow #6998, 6/30/76, L.C.R.C. Liber 4, Page 146; 6/25/76, Survey 506-38; H.W. Taft # 12032, 2/16/77, Survey 506-49; R.S. Macomber #27453, Survey 506-84A

3/4" Iron Pipe - "Witness Do Not Check. Verified from 1945 Survey by others.

- 10) 30" Oak S45°W 74.9
- 11) 36" Oak S40°W 95.4
- 12) Fence Corner West 34.0
- 7) Power Pole N85°E 34.6

Atwell-Hicks, R.J. Jagow #6998, 6/28/76, Survey 506-40; 6/7/79, Survey 507-94

3/4" Iron Pipe

- 7) Power Pole N85°E 34.6
- 12) Fence Corner West 34.0
- 13) 24" Elm Stump S50°W 60.0
- 10) 30" Oak \$45°W 74.9
- 11) 30" Oak \$40°W 95.4

Washtenaw Engineering, N.N. Fahrner #17620, 12/1/78, Survey R-4275; 8/19/86, Survey R-5486; 6/17/97, Survey R-7411

3/4" Iron Pipe

- 7) Power Pole N85°E 34.6
- 12) Fence corner West 34.0
- 13) 24" Elm stump S50°W 60.0
- 10) 30" Oak S45°W 74.9
- 11) 30" Oak S40°W 95.4

C. Wilson and Associates, C.C. Wilson # 13604, 3/10/86, Survey 85204; 2/16/87, Survey 87032 3/4" Iron Pipe

- 3) 30" Elm S54 1/2°W 46.7
- 7) Power Pole N88°E 34.5
- 8) Power Pole W'ly 29.8
- 9) 8" Oak S50°E 31.0



Washtenaw Co. CORREM L-2 P-336

RFA

ZUUIII

SECTION