SUHVEY & REMONUMENTATION

Liber 00001 Pase 0446 RM

- COOU-

MAY 0 9 1996

113.13 O D (Q)	LAND CORI	NER RECORDATION CERTIFI	CALE		-		
For corners in COMMISS	ION Filing Requ	irement of Act 74, Mich. P.A.	1970	,	- 1000 - 1		-7t-
WASHTENAW (County)	Located In:	Corner Code ≠≠		$\bigcap_{i=1}^{n}$		Mar 29	МАЅИП
Public Land Survey	T2S_R6E TR TR TR			DOY 1	The state of	1 34 PM	RECORCED ENAW COUN
	TR TR) SER		3	7.5
3. Miscellaneous S	T R		Register o	f Deeds S	Stamp	& File !	Number
4. Lot No, Reco	rded Plat		2 3	8 C D	E F	G H 1	J K L
do hereby certify that under requirer in lines 1 and 2 above were in concurrent manual of survey instruction Management or by a decree of a Couabove were in conformance with the Court of Law; established, re-est expressed below:	ments of P.A. 74, Michigan P.J. formance with regulations and of the United States Depart of Law and/or that the corrections of the Michigan Board ablished, monumented, re	11 JUNE 19 94 A. of 1970, the corner points mentione and rules therefore as required in the artment of the Interior, Bureau of Lander points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of -monumented, recovered, found a second and a second a second and a second and a second a se	ed 8 1	3 17 20 29	-2128	10	-11 12 13 24 24 25
NOTE: Not more than 4 corner	rs, all in the same town a	and range, may be recorded	''	- - - 		11}	

Description of original monument and accessories and/or subsequent restoration:

G.L.O.

on this certificate.

Set Stake

Date Unknown J.B. Davis

Hickory, 8" N 20° W Hickory, 8" S 30 °W

46.0

Date Unknown COUNTY WASHTENAW H. H. ATWELL

W. Oak, 5" Cherry, 18"

25.5 S.E. 51.5

5

SEE BACK OF THIS SHEET (NEXT PAGE) FOR CONTINUATION OF SECTION "A"

B. Oak, 1" S 521/4° W 25.6 Cherry, 4" S 79° W 32.0

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

IRON PIPE

BETWEEN 1983 AND 1986, IT APPEARS THAT THE 11/2" X24" IRON PIPE'S TOP HAD BEEN, MOVED BY THE GRADING OF GRAVEL, ABOUT 0.6' WEST. WASHTENAW ENG. CO. & ATWELL HICKS BOTH USED THIS NEW POSITION. ON THE 15 OF DECEMBER '93, WE ALSO FOUND A 1" BOAT SPIKE AT THE CORRECT POSITION, BY DIGGING WE FOUND ONLY THE BOTTOM OF THE 11/2" X24" IRON PIPE WAS IN THE ORIGINAL POSITION. ON THE 11 OF JUNE '94 WE SET A 1" X 24" IRON PIPE, USING THE REMAINING 5 WITNESS TAKEN PRIOR TO

Description of monument for corner and accessories established to perpetuate locating the position of the corner;

	PK & RT in NW sd, 18" Red Oak	N 35° E 45.19	8
SET A 1" X 24" IRON PIPE	PK & RT in DE Pole	N 55° E 101.35	13
	Nail in 12" Oak Stump	EAST 20.20	12
	Fd. 3/ Iron Pipe #13352 (new)	EAST 32.39	14
	PK & RT in N sd. 18" White Oak	S 70° E 26.00	3
	Nail in 40" White Oak	S 10° E 96.60	10
	Nail in 15" Red Oak	S 50° W 25.05	5
	Fd, 1/4" Iron Pipe (old)	WEST 32.69	9
	Fd. ¼" Iron Pipe # 17620	WEST 33.51	15
	C/L Joy Road (orig, 1½" I.P. in bricks)	NORTH 371.64	7

EKABSON ROFESSIONAL TOPESSIO!

I conclude that after careful study of the record documentation and field observations, that this corner is a careful and faithful perpetuation of the position of the original corner.

Signed by 19836

Surveyor's Michigan License No.

14 February, 1996

,i	L			4 10.	_{le} U¥≤	ti KIII		
1976 23 June	1975 September	1968 11 June	1934 10 January	DATE	spy-	CONTINUATI		
BOSS ENGINEERING CO. OSCAR BOSS Job#6762	CONTROL SURVEY ASSOC. INC. R. TIMOTHY TIETSEMA Job # 2SE06-75-270-M	ATWELL-HICKS, INC.	WASHTENAW COUNTY ROAD COMMISSION W.J. ARMSTRONG	SURVEYOR		CONTINUATION OF SECTION "A"		
#13574	#20712		#2444					
	٠			P.A. 74 L.C.R.C.				
S.E. 1/4 SEC. 36	N.W. % SEC. 6, SCIO	S.E. ¼ SEC. 36, WEBSTER N.E. ¼ SEC. 1, SCIO		LOCATION OF SURVEY	ANN ARBOR TOW A-1 (NORTI	1993 WASHTENAW C		
Found 1' Pipe	Found Iron	Found Iron	-	MONUMENT DESCRIPTION	ANN ARBOR TOWNSHIP TOWN 2 SOUTH, RANGE 6 EAST A-1 (NORTHWEST CORNER OF SECTION 6)	OUNTY REMONUME		
Spike N/S 16* Oak Spike N/WIS 12* Oak Spike W/S 16* Oak Iron Found Iron Found	No Witnesses	C/L Joy Road	SECTION MAP C/L Joy Road	WITNESSES	JTH, RANGE 6 EAST SECTION 6)	COUNTY REMONUMENTATION PROGRAM		
\$ 80° E 25.74 \$ 45° W 25.03 N 35° E 45.19 WEST 32.69 NORTH 371.70		NORTH 371.7	NORTH 371.7	BEARING & DISTANCE	1 1130	Ligh		
5 5 7		7	7	ID# COMMENT	I. John Jekabson P.S. # 19836 Roskelly, Jekabson & Assoc. P.C.	History compiled by: I. John Jekabson P.S. # 19836 Roskelly, Jekabson & Assoc. P.C		

1976 26 October

ATWELL-HICKS, INC. JOHN L. SNYDER Job#

#13352

Liber 4, Page 161 M - 1, Scio Twp.

Found Iron Pipe

Spike 16" W. Oak Spike 12" B. Oak Spike 38" W. Oak

\$71°E 25.99 \$5212°W 24.94 \$1113°E 96.60 WEST 32.67

დ ე თ ა

"MAPLE MEADOWS ESTATES" SUB. Liber 21, Pages 97, 98, & 99

1978 14 Nov.

WASHTENAW ENG. CO. NORMAN N. FAHRNER Job#

#17620

Liber 4, Page 161 M - 1, Scio Twp

1/2 Iron Pipe

14" W. Oak 12" B. Oak 36" W. Oak 12" Cherry 10" Oak

1983 12 April

WASHTENAW ENG. CO. NORMAN N. FAHRNER Job#?

#17620

1986 26 Sept

WASHTENAW ENG. CO. NORMAN N. FAHRNER Job # 20922

#17620

S. E. 1/4 SEC. 36

Found 11/2" Iron Pipe

Nail 10" Cherry Nail 14" Oak Nail 18" Oak Nail 12" Oak Nail 60" Oak

\$79°W 29.89 \$52½°W 24.53 \$71°E 26.58 EAST 20.78 \$30°E 96.57

Note that these witnesses indicated that the section comer is 0.6'± west of previous point.

S. W. 1/4 SEC. 31 NORTHFIELD TWP.

Found %" Iron Pipe

Nail 5" Oak Nail 4" Cherry Nail 14" Oak

S 45° W N 45° E

26.00 30.02 45.17

S. W. 1/4 SEC. 31 NORTHFIELD TWP.

Found 1" Iron Pipe

Nail in 16" Red Oak Nail in 18" White Oak Nail in 40" White Oak Nail in 14" Red Oak

N35*E S70°E S10°E S50°W

45.19 26.00 96.60 24.72

5 2 8

S 45° W EAST

S 71° E S 52° W S 11° E

27793

1983 8 April

ROSKELLY, JEKABSON & ASSOC., P.C. ! JOHN JEKABSON Job#83-3-93

#19836

1978 14 Sept.

ATWELL-HICKS, INC. ALLEN R. SUGGITT Job # 30610

P.E. # 12414

S.E. 12 SEC. 36, WEBSTER N.E. 12 SEC 1, SCIO