LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

		COMP
For corners	in	

WASHTENAW

Public Land Survey

COMMISSION FILE

HUN ZS I 34 PH 38 NOTH I BE OFFICE ANN COUNTY OFFI PH 18 1 PH 3 NOTH I BE IN THE I BE ANN COUNTY OFFI PH 18 THE I BE ANN COU

2. Property Controlling in Section

 in Section
 S
 T
 R

 Miscellaneous
 S
 T
 R

 Property in Sec.
 S
 T
 R

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _

Private Claims

I. JOHN JEKABSON in a field survey on

8 November 19 95

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1819 G.L.O. -T. WAMPLER SET POST

Red Oak, 15" Hickory, 12" S 04° W 14Lks N 22° E 24Lks

Date Unknown WASHTENAW

COUNTY ROAD COMMISSION

GRID BOOK - H.H. ATWELL

Iron Pipe

Maple, 6" S.E. Cor. House N.E. Cor. House

Elm, 6

10 11

12

S 60° W 64.5 N.E. 168.75 S.E. 164.5

N.E. Cor. House N.E. N.E. Cor. House S.E. Hickory, 6" N 62° Hickory, 10" N 22%

N 62° W 54.1 N 22½° W 68.9 N 31½° E 44.5

SEE BACK OF THIS SHEET (NEXT PAGE) FOR COMPLETE SECTION "A"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 5/8" STEEL BAR IN MON BOX

USING 4 WITNESSES FROM SECTION "A"

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Found 5/8" Steel Bar in Mon Box SET 1"X18" IRON PIPE W/REMON CAP OVER THE STEEL BAR

N 46° W 60.32 PK & RT in SW sd Util. Pole SW Cor. House N 44° E 145.34 Nail in 24" Apple N 45° E 77.97 PK & RT in S sd Util. Pole N 80° E :142.46 15 PK & RT in SW sd Util. Pole Nail in NE sd 12" Walnut S 60° E 122.46 16 S 52° E 58.43 8 PK & RT in SE sd 17" Elm S 60° W 82.61

I. JOHN
JEKABSON
PROFESSIONAL
SURVEYOR
NO.
19836

I conclude that after careful study of the record documentation and field observations, that this corner is accepted as the best available evidence of the position of the original corner.

19836

Signed by _______Surveyor's Michigan License No. _

14 February, 1996

APPROVES DATE _//- /3 - 95

Date

STATE BOARD OF LAND SURVEYORS, JAN. 21 REVISED MAY 14 REVISED JAN