## SECTION

JAN 22 8 38 AM '98

## LAND CORNER RECORDATION CERTIFICATE

2. Property Controlling S T R Liber 00002  in Section S T R R Register of Deeds Start R R R R R R R R R R R R R R R R R R R	PEGGY M. HAINES COUNTY OLERE REGISTER
2. Property Controlling S T R Liber 00002  in Section S T R R Register of Deeds Start R R R R R R R R R R R R R R R R R R R	- COON -
2. Property Controlling S T R Liber 00002 in Section S T R R Register of Deeds Start R R Register of Deeds Start R Register of Deeds Start R R R Register of Deeds Start R R R R R R R R R R R R R R R R R R R	- COPY - - COPY-
5. Private Claims  1. PATRICK L. HASTINGS in a field survey on NOV. 24.  3. Nov. 24.  4. The second in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	Liber 00002 Page 0127 RM Register of Deeds Stamp & File Number
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	2
A. Description of original monument and accessories and/or subsequent restoration:  1819 G.L.O. Field Notes and Plat Set Post 1) N 20° W 17 LKS W.O. 40°  1935 W. J. Armstrong, W. C. Lowe. Found a wood stake with 4 bricks set around it on end to form a box. Reset by driving an iron pipe into the stake. 2) N 35° E 45.1' Apple 10° 3) N 51° W 40.4' Elm 12° 4) N 43° W 41.1' W. Oak 4° 5) N 37° W 53.3' W. Oak 10° 6) North 31.7' ironwood 4"  2 Right-of-Way Place (SECHON & CONTINUED)	PATRICK L.  HASTINGS PROFESSIONAL SURVEYOR No. 37277

Found 1  $1/2^{\circ}$  iron pipe surrounded with brick witnessed iron and pulled. Dug and found no other evidence. No remaining witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1 1/2" iron pipe with 1"x18" iron pipe with remon. cap stamped #37277.

217.70° 14" SYCAMORE
33.40° UTIL POLE WITH NAIL
93.00° 18" OAK WITH NAIL
107.00° 19" OAK WITH PK
71.10° 12" OAK WITH NAIL N 70° E N 15° E N 35° W N 55° W S 58° W

APPROVED DATE 11/24 CO. REF.

After a careful study of the record documentation and field observations, made under my direct supervision, I find this corner as remonumented to be a careful and faithful perpetuation of the position of the original corner.

Date.

Surveyor's Michigan License No. .

FORM APPROVED BY MICHSOAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

## SECTION A CONTINUED

- COPY-

1972	Three	e surveys by	y Glenn E. '	Richard	#13040	
	From	Associated	l Engineers	and Sur	veyors, Inc.	
	Same	e witnesses	on both s	urveys.	Found Iron	Pipe.
	7)	N 40° E	41.70'	Nail in	Edison Pol	е
	8)	S 80° E	129.36'	Nail in	Sycamore	16"
	9)	S 50° E	38.85'	Nail in	Sycamore	16"
	10)	S 80° W	110.95'	Nail in	Sycamore	20"

- L.C.R.C. by Glenn E. Richard #13040
  From Associated Engineers and Surveyors, Inc.
  7) N 40° E 41.70' Nail in Edison Pole
  8) S 80° E 129.36' Nail in Sycamore 16"
  9) S 50° E 38.85' Nail in Sycamore 16"
  10) S 80° W 110.95' Nail in Sycamore 20"
- 1994 Right—of—way survey by Midwestern Consulting, Inc. Corner shown by symbol with distances to the hundredth of a foot. Corner was found using previous surveyor's witnesses.