SURVEY & REMONUMENTATION

JAN 25 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

RECORDED IN LIBER 04 PAGE 0236

MAY 5 10 25 AM '00

Shelley Myers

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in Lake

	Located in:	Corner Code#
1. Public Land Survey	T 18 N R 11 W	C-9
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

4. Lot No. _____ Recorded Plat _____

5. Private Claims _____

I, Robert L. Wetherell, in a field survey on March 17, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6		18	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11													
12		31	32	33	34	35	36						
13													

C-9 - Sec. corner common to Sections 19, 20, 29 & 30, T18N, R11W

A. Description of original monument and accessories and/or subsequent restoration:

1838 - J. Hodgson, G.L.O.
#1 - 8" Pine S67°E 8 Links
#2 - 8" Pine N48°W 8 Links

1904 - R.H. Hollister
"Set Stone in Ground".

1973 - C. Cole, LS 17615
Survey recorded L. 01, Pg. 186
Found 1" Pipe 37' South of centerline of road East & West.
#3 - 8" W. Oak N6°E 64.58'
#4 - 10" B. Oak N86°W 32.10'
#5 - 6" W. Oak S54°W 28.79'

1974 - John Myers, LS 14099
L.C.R.C. - Liber 02, Pg. 186
Survey recorded Liber 02, Pg. 186
Same witnesses as Cole in 1973.

1998 - R. Wetherell, LS 24624
1" Pipe
#6 - 6" Maple N26°E 3.88'
#5 - 11" W. Oak S07°W 28.78'
#7 - 10" Cherry S84°E 24.25'
#8 - 6" Maple N72°W 29.69'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:
I found a 1" iron pipe 37 feet South of centerline of East and West road. I also found old corner fence post (down) 16.5 feet West and 15.5 feet South. I was unable to locate Hollister's stone.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found stump, #4 Found dead, #5 Found in good condition, #6 Found in good condition, #7 Found in good condition, #8 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
I placed a Lake County Remon Cap over the 1" pipe, and is accepted as a careful and faithful reestablishment of the position of the original corner.

4" Maple N26°E 3.88' (60d spike E. side) #6
11" W. Oak S07°W 28.78' (60d spike E. side) #5
10" Cherry S84°E 24.25' (60d spike S. side) #7
6" Maple N72°W 29.69' (60d spike N. side) #8

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP
IN ACCORDANCE WITH P.A. 345
CHAIRMAN R.R.W.
DATE 4-11-2000

STATE OF MICHIGAN
ROBERT L. WETHERELL
LAND SURVEYOR
NO. 24624
MICHIGAN LAND SURVEYOR

Signed by Robert L. Wetherell Date 4-12-2000
Surveyor's Michigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING JANUARY, 1999