SURVEY & REMONUMENTATION

JAN 25 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

RECORDED
LAKE COUNTY MI
LIBER 004 PAGE 0235

MAY 5 10 25 AM '00

Shirley Myers
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in Lake _____

	Located in:	Corner Code#
1. Public Land Survey	T 18 N R 11 W	E-8
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

I, Robert L. Wetherell, in a field survey on March 17, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6		18	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11													
12		31	32	33	34	35	36						
13													

E-8 - ¼ Corner common to Sections 20 & 21, T18N, R11W

A. Description of original monument and accessories and/or subsequent restoration:

1838 - J. Hodgson, G.L.O.
#1 - 10" Pine N78°E 29 Links
#2 - 14" Pine S76°W 31 Links

1904 - R. H. Hollister
#3 - 18" W. Pine S52°W 50-3/4 Links
#4 - 15" W. Pine N42°E 52 Links
"Set stone with "X" on top".

1973 - C. Cole, LS 17615
Survey recorded L. 01, pg. 308.
Set by single proportionate method 2604.06 each way.
#5 - 12" B. Oak N42°E 69.10'
#6 - 6" B. Oak S53°E 57.18'
#7 - 6" Maple S46°W 38.58'

1979 - R.L. Wetherell, LS 24624
Unrecorded Survey File No. 3315-79.
Same accessories as Cole's in 1973.

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found Cole's ½" rebar 4 feet more or less West of centerline of North and South road. I found what I thought was Hollister's Pine Stump to the Southwest. I excavated (at Hollister's bearing and distance) an area 3' x 6' (6 feet deep) to find stone. I did not recover stone. I accepted Cole's ½" rod.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Gone, #5 Found stump, #6 Gone, #7 Found in poor condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced Cole's ½" rod with a ¾" x 24" rebar with Lake County Remon Cap, and is accepted as a careful and faithful reestablishment of the position of the original corner.

RATIFIED BY THE LAKE CO. PLAT REVIEW GROUP
IN ACCORDANCE WITH P.A. 345
CHAIRMAN R.S.W.
DATE 4-11-2000

10" W. Oak S66°W 60.30' (60d spike S.E. side)
12" Maple S27°W 115.01' (60d spike E. side)
4" Cherry N36°E 46.47' (center of tree)
8" W. Oak N03°W 78.23' (60d spike E. side)
10" Maple N66°W 112.24' (60d spike N. side)

STATE OF MICHIGAN
ROBERT L. WETHERELL
LAND SURVEYOR
NO. 24624
LICENSED LAND SURVEYOR

Signed by Robert L. Wetherell Date 4-12-2000
Surveyor's Michigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING JANUARY, 1999