LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co. 2 Corners.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 47 N. x S., R. 11 E. x W.	H-13, I-12
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 9-22, 9-16, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

H-13 Quarter Corner on Southside of Section 34, set by John Burt, D.S. in 1841. Bearings were: 10" Maple, N45°E, 31 lks. and 24" Birch, N7°W, 29 lks.

I-12 Quarter Corner between Section's 34-35, set by Geo. H. Cannon D.S. in 1853. Bearings were: Hemlock 12, N40°E, 24 lks. and Beech 12, S28°W, 20 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-13 Corner re-established midway and on line between two Section Corners. No evidence of original corner.

I-12 Corner re-established midway and on line between two Section Corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at both corners.

H-13 New Bearings; 14" Hemlock, S69°W, 8.9' and 12" H. Maple, S77°E, 16.8' and 12" S. Maple, S5°E, 33.5'.

I-12 Corner lies on West edge of planting road. No new bearings available.

SIGNED BY Billy D. Buckler DATE 9-8-78

Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

STATE OF MICHIGAN REGISTERED LAND SURVEYOR BILLY D. BUCKLER LAND SURVEYOR NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1973