SECTION

1997 Mackinac County Remonumentation Corner
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Located In: Corner Code #

___Mackinac___
(County)

1. Public Land Survey   T _43N_ R _1W_   _G-10_
       T ____ R ____   _____
       T ____ R ____   _____
       T ____ R ____   _____

2. Property Controlling   S ____ T ____ R ____   _____
   in Section   S ____ T ____ R ____   _____
3. Miscellaneous   S ____ T ____ R ____   _____
   Property in Sec.   S ____ T ____ R ____   _____

4. Lot No. _____ , Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28	●	27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, __David B. Guthrie__, in a field survey on _____ July 18 _____, 19 _97_____ ,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:
   1845: G.L.O. Survey by J.H. Mullett – Set Post and Referenced
       Hemlock 20 / S68W / 25
       Birch 4 / S74E / 14
   1994: Survey by Ronald Bischer – Found 1/2" Iron Rod and three old witnesses.
       Referenced –
       N54°E – 16" Cedar – 49.42'
       S85°E – 8" Fir – 36.60'
       N63°W – 6" Aspen – 35.15'
       West – 1/2" Iron Rod – 33.0'
       L.C.R.C. Recorded in Book D, Page 262.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
   1997: Remonumentation Survey by R.S. Scott Associates, Inc.
       Found 1/2" Iron Rod in road centerline.
       Referenced –
       (Exist.) S75°E – 8" Balsam – 36.38'
             N63°E – 20" Cedar – 47.60'
             S46°W – 10" Aspen – 53.90'
             N78°E – 15" Cedar – 47.33'

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON _____ 11-21-97

This corner position is compatible with County and local surveys. This corner
position is accepted as a careful and faithful perpetuation of the position of
the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
   1997: Placed 3" Mackinac County Cap stamped to identify the corner over 1/2" Iron Rod.
       Referenced –
       S75°E – 8" Balsam – 36.38'
       N63°E – 20" Cedar – 47.60'
       S46°W – 10" Aspen – 53.90'
       N78°E – 15" Cedar – 47.33'

(Seal: STATE OF MICHIGAN — DAVID B. GUTHRIE, LAND SURVEYOR NO. 22435, PROFESSIONAL SURVEYOR)

Signed by _____   Date __12-12-97__

Surveyor's Michigan License No. __22435__