SURVEY & REMONUMENTATION

1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Montcalm County Remonumentation Program

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED

21 DEC 93 3:11 P.M.

VIRGINIA L. KNEPPER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in MONTCALM (County) Located In: Corner Code #

1. Public Land Survey	Sec. 35	T 11	R 7	K-13, Cor. Com.
	and 36	T	R	
		T	R	
		T	R	
2. Property Controlling	S	T	R	
in Section	S	T	R	
3. Miscellaneous	S	T	R	
Property in Sec.	S	T	R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William Tingley a field survey on October 14, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

December 8, 1836, Noah Brookfield, from GLO notes
Set Post for Corners 35 and 36 South Boundary
Sugar 10" N46°W 36 links
Beech 10" N50°E 23 links
1884 H.M. Caukin, Deputy Surveyor from Page 375 of Field Notes at Montcalm County Register of Deeds
Reestablished from Southeast Corner 36-T11N R7W 80.08 chains and 160.16 chains from Corner 33 and 34 South Boundary T11N R7W and on straight line between 1 and 2 and 2 and 3 North Boundary of T10N R7W
Set Fire Clay mon
New Bearing Tree Pine Stump 30" N21-1/2°W
1960 G.M. Stevenson #13600
Found Fire Clay mon
Oak 24" S49°30'E 74.0'
Oak 15" N57°30'W 35.8'
Pine 12" N57°30'E 50.2'
4.6' North of Centerline Pavement
1969 R.J. Crater #16924
Found 2" Iron from G.M. Stevenson's witnesses of 1960
Power Pole Southeast 36'
Power Pole Northeast 71'
199.20' East to North Quarter Section 2 T10N R7W
1977, R.J. Crater #16924 -- found same as in 1969
1992 W.G. Tingley #30104
Found Railroad spike
East End Culvert N10°E 20.35'
Found Nail & Tag #25832 East side Power Pole S15°E 36.15'
Found Nail & Tag #25832 West side Power Pole N45°E 71.38'
1" Iron Pipe East 199.14'
1/4" Iron Rod S84°E 35.89'
Centerline East-West Road South 5.8'

SURVEY & REMONUMENTATION

1993

COMMISSION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Railroad Spike
Dug down 2.3', found Fire Clay mon, set magnet beside it
Accepted as corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set remonumentation and monument box over fire clay mon.
Nail and Tag #25832 East side Power Pole S15°E 36.56'
Nail and Tag #25832 West side Power Pole N50°E 71.05'
1" Iron Pipe East 199.14' (N Quarter Section 2 T10N R7W)
Oak 24" Stump S49 E 74.15'
Found nail Northwest Side Power Pole N65°E 100.85'

STATE OF MICHIGAN
WILLIAM G. TINGLEY
LAND SURVEYOR
NO. 30104
REGISTERED LAND SURVEYOR

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William G Tingley Date 23 November 1993

Surveyor's Michigan License No. 30104

LIBER 3 PAGE 80

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993