SURVEY & REMONUMENTATION

1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Montcalm County Remonumentation Program

For corners in Montcalm (County) Located In: Corner Code #

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED

21 DEC 93 3:11 P.M.

VIRGINIA L. KNEPPER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey Sec. 36 T 11 R 8 M-11, NE Corner
   T___ R___
   T___ R___
   T___ R___
2. Property Controlling S___ T___ R___
   in Section S___ T___ R___
3. Miscellaneous S___ T___ R___
   Property in Sec. S___ T___ R___

4. Lot No. ___, Recorded Plat ___
5. Private Claims ___

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, William Tingley a field survey on October 20, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

May 26, 1937, John Hodgson, Deputy Surveyor
Set Post
Beech 8" S36°W 28 links
Beech 8" N14°W 30 links
1884 H.M. Caulkin, Deputy Surveyor from Surveyor Notes of Montcalm County Register of Deeds
Found new Bearing Tree of 1878 when Bearing trees were plain: Pine Stump 25" N42-1/2 E 26 links
Set Fire Clay Mon on Hardpan Blacksmith Cinders around bottom
August 20, 1923, J.F. Doust, County Surveyor from Surveyor Notes of Montcalm County Register of Deeds
Corner was inquired of residents and found fire clay mon was plowed out and broken while graveled road was being constructed.
Drove piece of Gas Pipe and Broken Pump Handle in Center of Cinder
3" Maple bears N12°W 82.33'
April 6, 1990, G. Gray #17741, Liber 2, Page 299
Power Pole N60°W 95.57'
Guy Pole N20°W 104.3'
Maple 22" S15°E 102.2'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Gas Pipe and Broken Pump Handle Set in Nest of Rocks
Accepted Pipe as I.F. Doust Corner

SURVEY & REMONUMENTATION

1993

COMMISSION

STATE OF MICHIGAN
WILLIAM G. TINGLEY
LAND SURVEYOR
NO. 30104
REGISTERED LAND SURVEYOR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set remonumentation corner and monument box.
Nail & Tag in Power Pole N60°W 95.57'
Nail & Tag in Guy Pole N20°W 104.3'
Nail & Tag in 22" Maple, Westside S15°E 102.20'
No witness less than 200'

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William Tingley Date 23 November 1993

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993