SURVEY &
REMONUMENTATION

AUG 1 0 2005

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filling Requirement of Act 74, Mich., P.A. 1970

For corners in Lake (County)

		Located in:	Corner Code#
1. Public Land Survey		T18N R14W	H-11
		T__N R__W	
		T__N R__W	
		T__N R__W	
2. Property Controlling	S___	T__N R__W	
in Section	S___	T__N R__W	
3. Miscellaneous	S___	T__N R__W	
Property in Sec.	S___	T__N R__W	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

RECORDED
LAKE COUNTY, MI
18 OCT 2004 2:34:23 PM
SHELLY MYERS
REGISTER OF DEEDS

Liber 5 Page 325

Register of Deeds File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Robert L. Wetherell, in a field survey on August 5, 2004, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

H-11 ¼ Corner 27 - 34

A. Description of original monument and accessories and/or subsequent restoration:

1838 Sibley, G.L.O.
#1. 14" Hemlock N80°W 18 Lks.
#2. 14" Pine S85°E 17 Lks.

Undated County Survey Records
#3. 16" B. Oak N21°E 58'
#4. 10" B. Oak S63°E 44'

1919 & 1938 G. Johnson, Co. Surveyor
#3. 24" B. Oak N22°-30'E 55'
#4. 22" B. Oak S56°=30'E 44.3'

1957 G. Blass, L.S. 5489
Found 1 ¼" pipe from wit. by Johnson
#4. 18" B. Oak S57°E 44.00'
#3. 20" B. Oak N22°E 54.50'

1962 G. Shadko, Dept. of Conservation
Found 1 ¼" x 28" well point & old Brg. trees
Replaced with 4" x 36" pipe filled with concrete
#5. 8" Tw. W. Oak N43° - 15' W 57.9'
#6. 11" B. Oak S81°-30' E 74.1'

1964 R. Griffin, L.S. 13854
L.C.R.C., L.01, Pg. 122
Found monument by Shadko
#3. 27" B. Oak N22°E 55.15'
#7. 2" W. Oak N79°E 37.30'
#4. 21" B. Oak S56°E 44.52'
#5. 10" Tw. W. Oak N40°W 57.93'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found Shadko's 4" concrete monument on the northerly side of an old abandoned two track road. It checked well with the recovered accessories.

Condition of Accessories: #1, Gone, #2, Gone #3, Found stub, #4, Found stump, #5, Found in good condition,#6, Found stump, #7, Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accepted the 4" concrete monument as a substantial mark for the corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

14" & 1 Tw. R. Oak	N40°W	57.80' (60 d. spike in SW side)	#5
6" W. Oak	N82°E	37.22' (60 d. spike in N side)	#7
5" Maple	N35°E	52.02' (60 d. spike in NW side)	
6" Maple	S20°W	52.65' (60 d. spike in E side)	

STATE OF MICHIGAN
ROBERT L. WETHERELL
PROFESSIONAL SURVEYOR
No. 24624
LICENSED PROFESSIONAL SURVEYOR

Signed by Robert L Wetherell Date 10-18-04
Surveyor's Michigan License No. 24624

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP IN ACCORDANCE WITH P.A. 345
CHAIRMAN R.K.W. DATE: 10-12-04

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING JANUARY, 1999