LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Baraga

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 48 N. S., R. 32 E. W.	L 9, M 8, & M 9
2. PROPERTY CONTROLLING IN SECTION 24	,T. 48 N. S., R. 32 E. W.	16
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19__, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corners L9, M8, & M9: No evidence of original posts or accessories. At L9, no subsequent monuments found. At M8, found a 3"x3"x5' squared cedar post as set by unknown party. At M9, found an approximate corner wood post N85°E 19.7 ft. from corner.

Corner 16: Not established in original survey nor subsequently apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner L9: Re-established 12/4/72 on line between section corners 39.148 ch. to E and to W.

Corner M8: The found post checks perfectly in alignment and proportionate distance between Sec. corners 119.311 ch. to N and to S, therefore, accepted it and on 12/4/72 replaced the monument.

Corner M9: Re-established 9/22/71 on line between section corners 159.082 ch. N and 79.541 ch. S.

Corner 16: Established 9/21/71 on line between Sec. corner 19.574 ch. E and 1/4 corner 19.574 ch. W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for all four corners: 1" I.D. x 36" iron pipe with 4" aluminum cap.

Witnesses for Corner L9:	Sugar Maple	12	S64°W (mag.)	30.8 ft.	"1/4S, NBT"
	Sugar Maple	6	N61°E (mag.)	20.1 ft.	"1/4S, NBT"
Witnesses for Corner M8:	Sugar Maple	6	S21°E (mag.)	9.8 ft.	"1/4S, NBT"
	Sugar Maple	8	N 4°E (mag.)	10.1 ft.	"1/4S, NBT"
Witnesses for Corner M9:	Tamarack	7	N29°W (mag.)	10.8 ft.	"S19, NBT"
	Tamarack	8	S77°W (mag.)	28.8 ft.	"S25, NBT"
	B. Spruce	8	N76°W (mag.)	12.2 ft.	"S24, NBT"
Witnesses for Corner 16:	Sugar Maple	6	S53°W (mag.)	3.4 ft.	"1/16S, BT"
	Sugar Maple	6	N32°E (mag.)	4.9 ft.	"1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Keith L. Sackett CHIEF OF SURVEY PARTY DATE March 2, 1973

APPROVED AND SIGNED BY Arthur O. Enger MICHIGAN REGISTERED LAND SURVEYOR DATE March 2, 1973 (SEAL)

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

Form No. ML M736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS