LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF –:	LOCATED IN –:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. S., R. 13 E. W.	C-4, B-5
2. PROPERTY CONTROLLING IN SECTION 7	T. 26 N. S., R. 13 E. W.	7, 5, 6
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 11, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent accessories~~

B. Continued: 5 Reestab N1/8 cor on N-S¼ line S14°10'W 1.02' from 1972 position (See 1981 corner record for E¼ cor., SE cor & S¼cor of Sec. 7.

C. Continued:

B-5

Adjusted DNR mon. & ced. post		
17" Cherry	N20°E	46.0
9" Maple	N75°E	36.8
9" Maple	S20°W	19.3

6

Adj. 1" x 36" pipe & ced. post w/loc tag		
7" R. Pine	N80°W	87.2
7" R. Pine	S60°W	70.2
N-S fn.	East	2'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-4 Reestab. E¼ cor. of Sec. 7 midway & on line bet NE cor of Sec. 7 as recovered & Wit in May 1972 & SE cor of Sec. 7 as reestab. in 1981 (See G-5 per Act 74, P.A. 1970). E¼ cor of Sec. 7 as estab. in error by (C.F.R.) in 1972 was adjusted S15°32'W4.41' from 1972 position. A corner fence post (irregular fence N & E) is East, 44'±.

B-5 Reestab S¼ cor of Sec. 7 at single proportion to U.S. (G.L.O.)bet SW cor of Sec. 7 as recovered & Wit in May 1972 & SE cor of Sec. 7 as reestab. in 1981 (See G-5 per Act. 74, P.A. 1970). S¼ cor of Sec. 7 as estab. in error by C.F.R. in 1972 was adjusted S15°34'W 4.10' from 1972 position.

7 Reestab. N1/8 cor on E line of Sec. 7 S15°14'W 2.21' from 1972 position (see 1981 corner record for E¼ of Sec. 7, C-4).

6 Reestab ctr of NE¼ of Sec. 7 S15°14'W 1.64' from 1972 position (see 1981 cor record for E¼ cor, SE cor & S¼ cor of Sec. 7).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-4

Adj. DNR mon. (buried 0.5)		
14" Ironwood	S65°W	47.6
12" Maple	S65°E	30.4
13" Maple	N65°E	42.8
Ced. Post w/loc tag	West	33'±
Ctr line N-S Sand Rd.	West	6'±

7

Adj. 1" x 36" pipe & ced. post w/loc tag.		
20" Apple	S80°W	89.0
17" Cherry	S05°W	81.8
14" Maple	N25°W	74.8
Ctr. line N-S Rd.	E	14'±
Old fn to W (down)	S	25'±

5

Adj. 1" x 36" pipe & ced. post w/loc tag.		
10" Maple	N60°W	11.5
14" Cedar	S05°W	12.6
16" Cedar	S75°W	54.5
Ctr. line Co. Rd. 669	East	162'±

SIGNED BY Carl F. Roser 02-10-82 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 (SEAL) REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

INLAND TOWNSHIP
BENZIE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET