LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 17 N., R. 5 W.	E-10; E-11; C-11
2. PROPERTY CONTROLLING IN SECTION 29	T. 17 N., R. 5 W.	14; 15
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 16, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

C. Continued:

15

Set 5/8" rod w/RLS cap

8" Red Pine	N68°E	102.5
4" Poplar	S60°E	23.75
Cedar post	North	25'

C-11

Left tile/iron in place, added RLS cap

PK nail, 10" Maple	N72°E	44.56
PK nail, 10" Maple	N18°W	31.57

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-10 Restored this corner with reference to Section corner and N1/8 cor. (fence corner) on East section line. Falls near old N-S fence line in swamp, but nothing was found for previous corner monument.

E-11 Set corner by single proportionate measurement between the restored S1/4 of Sec. 29 and the found SE corner of Sec. 28. Unable to locate any positive evidence of the Johnson 1903 surveyor and subsequent monument.

14 Set by standard survey procedure for the subdivision of sections.

15 Set by standard survey procedure for the subdivision of sections.

C-11 Fd. tile with iron rod at corner, probably as restored by Johnson in 1903, or a subsequent local survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-10

Set DNR mon.

5" Cedar	N02°E	15.0'
5" Cedar	N39°E	13.6'

E-11

Set DNR mon.

6" Cedar	S50°W	16.9'
5" Cedar	N40°W	12.2'

14

Set 5/8" rod w/RLS cap

6" Cedar	S77°W	3.4'
10" Cedar	S39°E	15.1'

SIGNED BY Kenneth J Ostling DATE 3-12-81

STATE OF MICHIGAN KENNETH J. OSTLING LAND SURVEYOR NO. 10068 (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CLARE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET