# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF—: | LOCATED IN—: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY | T. 33 N. S., R. 5 E. W. | M-6,L-5,M-5,M-7 |
| 2. PROPERTY CONTROLLING IN SECTION 14 | ,T. 33 N. S., R. 5 E. W. | 2 |
| 3. MISCELLANEOUS PROPERTY IN SECTION | ,T. N. S., R. E. W. | |
| 4. LOT NO. , RECORDED PLAT | | |
| 5. PRIVATE CLAIMS | | REGISTER OF DEEDS STAMP AND FILING NUMBER |

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 18, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

M-7

Fd. 1" pipe (flush).

| | | |
|---|---|---|
| 26" Maple | N35°W | 166.60 |
| 9" Maple | N80°W | 92.7 |

2

Set 5/8" X36" re-rod w/RLS cap (buried 0.4)

| | | |
|---|---|---|
| 8" Cherry | N55°E | 49.53 |
| P. Pole | S60°E | 109.00 |
| 1/2" Pipe | N50°W | 16.00 |
| CTR. line E-w Gr. Rd. | S | 5'± |
| Set Cedar Post | N | 16.5' |

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M-6 Recovered M. Schaaf pipe monument (Dept. RLS & Forester-1930's) and replaced with DNR monument. Position fits E.A. Robinson data 1/2 mile south (1905) and 1/2 mile north(1901).

L-5 Re-estab. N1/4 Cor.-Sec. 13-midway & on line between recovered NE & NW corners of S-13.

M-5 Recovered M. Schaaf pipe monument (Dept. RLS & Forester-1930's) and replaced with DNR monument. Position fits E.A. Robinson data to south dated 1901.

M-7 Fd. 1" pipe (buried-flush) in Golf Course fair-way tee. Corner fits tie in plat of "Springbrook Hills No. 2" and survey by E.A. Robinson in Oct. 1905 for Town Line Road See dwg. #3-13-33-5.

2 Estab. NE Cor. of NW¼ of NE¼ of Sec.14 midway and on line between the NE corner & N¼ corner of Sec. 14.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-6

Fd. Schaaf mon; replaced w/DNR mon & ced. post

| | | |
|---|---|---|
| 5" Maple | S05°E | 4.8 |
| 5" Maple | N80°E | 14.2 |
| 6" Maple | N35°W | 22.9 |

L-5

Set DNR mon & ced. post

| | | |
|---|---|---|
| 7" Oak | S65°W | 28.4 |
| 6" Maple | S60°E | 5.5 |
| 7" Maple | N10°W | 41.1 |

M-5

Fd. 1" pipe in conc. Replaced w/DNR mon. & ced. post

| | | |
|---|---|---|
| 7" Ir. Wood | South | 15.1 |
| 8" Maple (twin) | N30°E | 12.7 |
| 4" Maple | S75°E | 35.0 |

SIGNED BY Carl F. Roser 01-12-82 DATE

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET