LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE	ER
1. PUBLIC LAND SURVEY	T. 34 N., R. 7 W.	E-4; F-4	
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION 9	T. 34 N., R. 7 W.	USMC 1369.5' N. of E-4 USMC 2534.4' N. of F-4 USMC 2513.5' W. of G-3	
4. LOT NO. , RECORDED PLAT			
5. PRIVATE CLAIMS			

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on June 1, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent restoration:~~

C. (Continued)

USMC 2534.4' N. of F-4
Set 1" x 36" pipe & steel Fence Post

10" Cedar	S89E	35.22'
16" R. Pine	S32E	42.75'
18" R. Pine	S06W	50.63'
℄ US-31	Due S	96.6'

USMC 2513.5' W. of G-3
Set DNR Mon. & steel Fence Post

4" Cedar	N71E	37.90'
7" Tw. Cedar	S64W	25.70'
10" W. Pine	N84W	12.50'
10" W. Pine	N44E	10.55'
Ctr. US-31	Due S	65±'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-4 Recovered Consumers Power corner of record.

F-4 Found ½" pipe and stone mound, per M. Feindt survey for Consumers Power Co.

USMC N of E-4 Recovered ½" pipe; fits MDSH survey data.

USMC N of F-4 Established corner at intersection of N-S ¼ line and U.S. meander line.

USMC W of G-3 Found position for USMC from MDSH survey data. Restored corner from same.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-4
Fd. Cons. Power Mont.
Set steel Fence Post

4" Cedar	N68E	8.7'
6" Cedar	S21E	13.8'
7" Cedar	S83W	34.6'

in old N-S fence line

F-4
Fd. ½" pipe, Added 1" x 36" pipe and steel Fence Post

3"x8' steel fn. post	S06E	81.5'
8" Cedar	N21E	81.15'
℄ N-S b.top road	Due W	33.0'

USMC 1369.5' N. of E-4
Fd. ½" pipe, Added DNR Mon. and steel Fence Post

Power Pole	S12W	75.80'
7" Cedar	S57W	7.20'
10" Cedar	S65E	31.45'
Ctr. US-31	Due S	208±'

in old N-S fence line

SIGNED BY Carl F. Roser DATE 12-17-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

(SEAL)

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR NO. SEAL 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM736
DUPLICATOR PROD. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS