LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 40 N. ~~S.~~ R. 29 ~~E.~~ W.	H 9 & I 9
2. PROPERTY CONTROLLING IN SECTION 22	T. 40 N. ~~S.~~ R. 29 ~~E.~~ W.	16
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19 , established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner H9:	Wood post	Not found.	No subsequent monuments found.	
	Cedar 10 S70W 12.	" "	No subsequent accessories found.	
	Birch 15 N21W 21.	" "	" " " "	
Corner I9:	Wood post	Not found.	No subsequent monuments found.	
	Hemlock 10 N62E 18.	" "	No subsequent accessories found.	
	Birch 25 S50E 25.	" "	" " " "	

Corner 16: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner H9: Re-established 7/6/72 on line between sec. corners 40.320 ch. to E and to W. Cedar stump S70°W 11 lks. matches original BT, but no proof.

Corner I9: Re-established 7/5/72 on W'ly extension of a line joining existing monuments at S 1/4 cor. and SE sec. cor. of Sec. 23, at a distance equal to that between the aforementioned monuments. Found this position to be more consistent with field note calls to natural features than is the case with proportional measurements. Corner falls on side of a hill, as per original field notes

Corner 16: Established 7/5/72 on line between 1/4 cor. 20.160 ch. W and sec. cor. ‖20.160 ch. E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for all three corners: 1" I.D. x 36" iron pipe with 4" aluminum cap.

Witnesses to Corner H9: Cedar 6 N ½°E (mag.) 18.6 ft. "1/4S, NBT"
Cedar 7 S 74° W (mag.) 28.1 ft. "1/4S, NBT"
** Cedar 5 S 8½° E (mag.) 13.1 ft. "1/4S, NBT"

Witnesses to Corner I9: Sugar Maple 5 N 77°E (mag.) 10.1 ft. "S23, NBT"
Sugar Maple 7 S 54°E (mag.) 43.0 ft.* "S26, NBT"
Sugar Maple 6 S 1° W (mag.) 12.6 ft. "S27, NBT"

*Slope measurement. **Monument set in mound of stones.

Witnesses to Corner 16: W. Ash 6 N14°E (mag.) 8.6 ft. "1/16S, BT"
Sugar Maple 5 S67°W (mag.) 8.8 ft. "1/16S, BT"
Y. Birch 5 S30°E (mag.) 16.2 ft. "1/16S, BT"

SIGNED BY DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY DATE

APPROVED AND SIGNED BY Arthur O. Enger MICHIGAN REGISTERED LAND SURVEYOR DATE April 12, 1973

Arthur O. Enger (SEAL)

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

Form No. ML M735
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS