SURVEY &
REMONUMENTATION

1993

COMMISSION

GRATIOT CO. MICH.
RECORDED

'93 DEC 20 PM 12 24

Janet M. Davis
REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970
Gratiot County Remonumentation Program

For corners in Gratiot (County)

	Located In:	Corner Code #
1. Public Land Survey	Sec. 31 T 11 R 4	C-13, SE corner
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William Tingley a field survey on October 23, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
April 2, 1831, Robert Clark, Jr., Deputy Surveyor
Set post at Corner, Section 31 and 32
Beech 13" N60°E 64 links
Beech 8" N49-1/2°W 25 links
1878 R.J. Fraker, County Surveyor, Book B, Page 270 from Record of Minutes of Survey of Gratiot County Drain Commission
Found old stake and renewed as good.
Cedar fence post 10" N38°
Double oak 8" N71-1/2°E
March 12, 13 and 14, 1888, D.W. Altenburg, Deputy Surveyor, Book C, Page 148 from Record of Minutes of Survey of Gratiot County Drain Commission
Found pine stump set by Fraker, 36" S12°E 25-1/2 links
Cherry 10" N22.3'
Oak 10" N10°E 62'
Twin Oaks N40°E 47.7'
May 8, 1974, David B. Whittier, #10070, Liber 1, Page 127 of land Corner Recordation Book
Found 3/4" Rod 0.8 deep raised with 3/4" pipe. Set in mon box.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Accepted as corner. Found 3/4" pipe in mon box by David B. Whittier #10070, Liber 1, Page 127 of Land Corner Recordation Book.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set remonmumentation corner in mon box.
Nail and tag North Side Power Pole S48°E, 98.0'
Nail and tag Northwest Side 28" Oak N7°E 62.10'
Nail and tag Eastside 14" Oak N70°W 24.15'
N 1/4 corner T10N-R4W W 228.8'
Corner is 1' North of Centerline

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

STATE OF MICHIGAN
WILLIAM G. TINGLEY
LAND SURVEYOR
NO. 30104
REGISTERED LAND SURVEYOR

Signed by William G Tingley Date November 30, 1993
Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993