LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N., R. 12 W.	I-5
2. PROPERTY CONTROLLING IN SECTION 10	,T. 26 N., R. 12 W.	9; 13; 16
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on January 20, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent restoration:~~

C. (continued)

16

Set P.K. nail in bit. cap, conc. pavement

1" Pipe	N22°W	81.9
1" Pipe	N40°E	53.2
10" Cedar	S37°E	78.0
8" Twn.Ced.	S48°E	99.6
Center line US-31 Due S		0.8

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-5 Found 1/2-inch pipe; old corner of record and more recently used by R.L.S. Fraser.

9 Established 1/16 corner equidistant and on line between center of Sec. to W 1/4 line to E. N-S fence remains, due W, 11'.

13 Established center of SE¼ per standard B.L.M. instructions. Corner fits split of R.O.W. fences to South and old fence to North. Set 1/2"x18" & 1"x36" pipe S87°48'E, 16.50' and 33.00'. Set 1"x36" pipe, N87°48'W, 33.00.

16 Restored corner equidistant and on line between ¼ corner west & sec. corner east, which fits line of occupation to N. Also description for corner H-5.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-5

Found ½" pipe in blacktop approach to railroad

℄ RR Track	SE'ly	8.9
RR Xing sign	S80°W	71.9
Power Pole	N13°W	35.00

9

Set 1"x36" pipe, cedar post w/loc. tag

12" Maple	N19°W	38.7
7" Maple	S33°W	29.5
9" W. Pine	S85°E	59.5

Set 1"x36" pipe S87°49'E 33.00

13

Set 1¼"x36" pipe, cedar post w/loc. tag

10" Maple	S78°W	53.8
9" Oak	S51°E	51.2
12" Maple	N09°W	20.1
8" R. Pine	N60°E	46.7

SIGNED BY Carl F. Roser 9-3-75 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR DATE _____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

GREEN LAKE TOWNSHIP
GRAND TRAVERSE COUNTY

Form No. ML M735

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN 26 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS