LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 42 N. ~~S.~~ R. 31 ~~E.~~ W.	L 11
2. PROPERTY CONTROLLING IN SECTION 36	,T. 42 N. ~~S.~~ R. 31 ~~E.~~ W.	1 & 2
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19___, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19___, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner L 11: Cedar post (Not found)
Cedar 14 N74W 30 (" " No subsequent accessories found.)
Fir 8 S48E 12 (" " " " " "

Found a 2" x 2" x 4' squared post N68°W .64 ch. for an approx. corner.

Corners 1 & 2: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner L11: Re-established 8/16/73 on line between original section corner 39.960 ch. W and a sec. corner of recent record 39.081 ch. E. The 39.960 ch. is record distance less apparent index error and was used (rather than proportionate measure) because of lack of confidence by this reporter in the Sec. Cor. on E. twp. boundary as being the original corner; latitude appears consistent with other original evidence found in this twp., but departure is not.
Corner 1: Established 5/17/74 on line between Sec. Cor. 19.980 ch. W and 1/4 cor. 19.980 ch. E.
Corner 2: Established 5/17/74 on line between 1/4 cor. 19.980 ch. W and Sec. Cor. 19.101 ch. E. All discrepancy, less index error, was put in the E quarter-mile of this sec. line, because of condition noted in Corner L11.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner L11: 1" I.D. x 38" iron pipe with 3½" aluminum cap.
W. Pine 8 N49½°E (mag.) 48.0 ft. "1/4S, NBT"
W. Pine 6 N72½°W (mag.) 31.2 ft. "1/4S, NBT"
Corner 1: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
Red Maple 5 S56°W (mag.) 16.6 ft. "1/16S, BT"
Red Maple 4 N62°W (mag.) 9.9 ft. "1/16S, BT"
Corner 2: 1" I.D. x36" iron pipe with 3½" aluminum cap.
Twin Sugar Maple 6 S37°W (mag.) 6.2 ft. "1/16S, BT"
Twin Sugar Maple 5 S70°E (mag.) 7.0 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY Arthur O. Enger MICHIGAN REGISTERED LAND SURVEYOR DATE July 31, 1974

Arthur O. Enger
Michigan Department of Natural Resources

STATE OF MICHIGAN ARTHUR O. ENGER LAND SURVEYOR No 13581 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

Form No. MLM736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS