# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF–: | LOCATED IN–: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY _____ | T. 42 N. ~~S.~~ R. 31 E. ~~W.~~ | L 3 |
| 2. PROPERTY CONTROLLING IN SECTION 1 | ,T. 42 N. ~~S.~~ R. 31 E. ~~W.~~ | 15 & 16 |
| 3. MISCELLANEOUS PROPERTY IN SECTION _____ | ,T. _____ N. S., R. _____ E. W. | |

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on see below 19__, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner L3: Y. Birch post (Not found. Found possible point of old wood post.)
Sugar 10 S40W 25 ( " " No subsequent accessories found.)
Fir 8 N50E 28 ( " " " " " " )

Corner 15 & 16: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner L3: Re-established 5/21/74 on line between Sec. Cor. 40.120 ch. to E and to W. Corner falls about 3 ft. W of construction centerline of N&S county road. While digging hole for corner monument, found a pointed 1"x3" piece of round wood in the undisturbed natural soil beneath the road bed, which may have been from an old post.
Corner 15: Established 5/31/74 on line between Sec. Cor. 20.060 ch. W and 1/4 cor. 20.060 ch. E.
Corner 16: Established 5/31/74 on line between Sec. Cor. 20.060 ch. E and 1/4 cor. 20.060 ch. W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner L3: 1" I.D. x 24" iron pipe with 3½" aluminum cap. (Top 6" below surface.)
Red Pine 12 N45°E (mag.) 54.5 ft. "1/4S, NBT"
Red Pine 9 S78°E (mag.) 38.8 ft. "1/4S, NBT"
Corner 15: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
W. Pine 10 N12°W (mag.) 75.1 ft. "1/16S, BT"
W. Birch (1 of a clump) 13 S61°W (mag.) 79.8 ft. "1/16S, BT"
Corner 16: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
Sugar Maple 5 N70°W (mag.) 8.4 ft. "1/16S, BT"
Sugar Maple 6 S57°W (mag.) 16.0 ft. "1/16S, BT"
Sugar Maple 8 N72°E (mag.) 41.2 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE November 26, 1974
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
Michigan Department of Natural Resources

STATE OF MICHIGAN ARTHUR O. ENGER LAND SURVEYOR No 13581 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

Form No. MLM736
DENNIS PRINT SHOP, S. CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS