LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 43 N. ~~S.~~, R. 31 ~~E.~~ W.	C3
2. PROPERTY CONTROLLING IN SECTION 8	,T. 43 N. ~~S.~~, R. 31 ~~E.~~ W.	1
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner C3 (Section Corner 5, 6, 7, & 8, T43N, R31W):
Cedar post (Not found. Found WMPC concrete monument.)
Spruce 12 N 6W 42 (" " No subsequent accessories found.)
Cedar 10 S15E 38 (" " " " " ")
Corner 1 (West 1/16 corner between Sections 5 & 8, T43N, R31W):
Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner C3: According to WMPC maps, monument was set by reference to ties noted on old RR maps, but nothing else is known about it. It appears to be more or less consistent with other corners in the area. Monument re-witnessed on 9/24/75.

Corner 1: Established on line between Sec. Cor. 19.925 ch. W and calculated 1/4 corner 19.925 ch. E. Monument placed on 9/26/76.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner C3: Concrete monument with WMPC brass marker
Tamarack 15 N49°W (mag.) 90.9 ft. "S6, NBT"
Tamarack 20 N56°E (mag.) 87.7 ft. "S5, NBT"
WMPC Power Pole #N61-2160 N14½°W (mag.) 52.06 ft. to tack with 3/4" brass washer stamped "WITNESS MARK"
Corner 1: 1" I.D.x36" iron pipe with 3 3/4" aluminum cap.
Tamarack 4 S37°E (mag.) 25.3 ft. "1/16S, BT"
Tamarack 2 S59°W (mag.) 50.4 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE March 30, 1976
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

Arthur O. Enger
Michigan Department of Natural Resources

STATE OF MICHIGAN ARTHUR O. ENGER LAND SURVEYOR No 13581 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET