LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. _____ N. S., R. _____ E. W.	
2. PROPERTY CONTROLLING IN SECTION 36	,T. 43 N. ~~S.~~ R. 32 ~~E.~~ W.	3, 4, & 5
3. MISCELLANEOUS PROPERTY IN SECTION _____	,T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner 3 (North 1/16 corner between Sections 35 & 36, T43N, R32W):
Corner 4 (Center of NW¼ of Section 36, T43N, R32W):
Corner 5 (North 1/16 corner on N & S 1/4 line of Sec. 36, T43N, R32W):

Corners 3 & 5 not established in original survey nor subsequently, apparently. Corner 4 established approximately at least twice previously: Found a 1" iron pipe & 6" wood post N55°E 17.7 ft. and a 1/2" iron pipe N16W 27.5 ft. from corner position reported herein.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner 3: Established 9/24/74 on line between Sec. Cor. 19.963 ch. N and 1/4 cor. 19.963 ch. S.
Corner 4: Established 9/23/74 at computed intersection of quarter-quarter section lines.
Corner 5: Established 9/19/74 on line between Center 1/4 cor. 20.007 ch. S and N 1/4 cor. 20.007 ch. N.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for all three corners: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
Witnesses for Corner 3: Tamarack 6 N89°W (mag.) 27.8 ft. "1/16S, BT"
Tamarack 5 N47°E (mag.) 10.4 ft. "1/16S, BT"
Witnesses for Corner 4: White Birch 12 S55°E (mag.) 25.5 ft. "1/16S, BT"
Red Maple 6 S35½°W (mag.) 21.4 ft. "1/16S, BT"
Witnesses for Corner 5: White Spruce 8 S10°W (mag.) 10.0 ft. "1/16S, BT"
Red Maple 5 N70°E (mag.) 21.5 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE March 30, 1976
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

STATE OF MICHIGAN ARTHUR O. ENGER LAND SURVEYOR No 13581 REGISTERED LAND SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET