LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 44 N. S., R. 34 E. W.	H3 & I3
2. PROPERTY CONTROLLING IN SECTION _____	,T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	,T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner H3 (¼ corner between Sections 3 & 10, T44N, R34W):
Wood post (Not found. See B for subsequent monument.)
Sugar 10 S15W 83 (" " . No subsequent accessories found.)
Cedar 12 N20E 105 (" " " " " " .)

Corner I3 (Section Corner 2, 3, 10, & 11, T44N, R34W):
Wood post (Not found. No subsequent monuments found.)
Sugar 14 N35E 7 (" " " " accessories " .)
W. Pine 40 S40W 19 (Found. " " " " .)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner H3: Re-established 6/2/77 on an old E'ly & W'ly fence line, S89°40.1'E 40.455 ch. from Sec. Cor. 3, 4, 9, & 10 and S89°47.6'W 40.455 ch. from Sec. Cor. 2, 3, 10, & 11. The fence line was given some recognition for latitude, but otherwise the mid-point distance was used. (Straight-line mid-point falls 12.55 ft. N) Found a 3"x3"x3' squared cedar post S72°W 35.2 ft. for an approx. corner.

Corner I3: Re-monumented corner on 5/13/76, from rotted remains of original BT stump, identified by position in relation to an original M.C. bearing S0°22.6'E 49.898 ch. (Record 49.86 ch.) Corner is on S side of E&W County Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner H3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap
Twin Elm 12 N59°W (mag.) 97.5 ft. "¼S, NBT"
Elm 15 S78°W (mag.) 100.6 ft. "¼S, NBT"
Declination 0°50' East

Corner I3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap
Sugar Maple 4 S29°W (mag.) 51.7 ft. "S10, NBT"
W. Birch 14 S77°E (mag.) 11.6 ft. "S11, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ (CHIEF OF SURVEY PARTY / MICHIGAN REGISTERED LAND SURVEYOR) DATE August 1, 1977

Arthur O. Enger
Michigan Department of Natural Resources

STATE OF MICHIGAN ARTHUR O. ENGER LAND SURVEYOR No 13581 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION JAN 28 1971
REVISED MAY 4 1975

MAY CHECK SECTION BACK OF ATTACHED SHEET