LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 44 N. ~~S.~~, R. 34 ~~W.~~	J7
2. PROPERTY CONTROLLING IN SECTION 23	,T. 44 N. ~~S.~~, R. 34 ~~W.~~	2
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 22, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner J7 (¼ corner between Sections 14 & 23, T44N, R34W):
Wood post (Not found. See B for subsequent monument.)
Sugar 20 S15E 35 (" " . No subsequent accessories found.)
Sugar 10 N21W 38 (" " " " " ")

Corner 2 (East 1/16 corner between Sections 14 & 23, T44N, R34W):
Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner J7: Re-established on line between Sec. Cor. 39.767 ch. E and Sec. Cor. 39.767 ch. W. Doubtless the original corner was at unequal distances on (or off) the section line, but there is no way to tell the direction or amount of discrepancy, thus I set the corner at mid-point. Found a 4"x4"x4' squared cedar post (probably L.E.S. control post) S43°E 66.1 ft., which has been used for the corner.

Corner 2: Established on line between Sec. Cor. 19.884 ch. E and ¼ cor. 19.884 ch. W. Found a 15" cedar blazed on 4 sides N15°E 21.3 ft., for an approx. corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner J7: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap
Ironwood 8 N51°E (mag.) 10.1 ft. "¼S, NBT"
Sugar Maple 8 S74°W (mag.) 15.0 ft. "¼S, NBT"

Corner 2: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap
Cedar 16 S27°E (mag.) 12.3 ft. "1/16S, BT"
Cedar 16 N3°E (mag.) 4.7 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE July 28, 1977

MICHIGAN REGISTERED LAND SURVEYOR

Arhtur O. Enger

Michigan Department of Natural Resources

STATE OF MICHIGAN ARTHUR O. ENGER LAND SURVEYOR No 13581 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET