Date MAR. 11, 1998

West 1/4 Corner of Section 19, Waterloo Township

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

#2064441
Liber 1563 Page 987
Page 1 of 1
Jackson Co., MI
Recorded
03/12/1998 12:00P
Minda Reilly
Register of Deeds

For corners in
JACKSON (County)

Located In: Corner Code #

1. Public Land Survey T1S R2E A-8
   T___ R___
   T___ R___
   T___ R___
2. Property Controlling in Section S___ T___ R___
3. Miscellaneous Property in Sec. S___ T___ R___

SURVEY & REMONUMENTATION
SEP 16 1998
SECTION

Register of Deeds Stamp & File Number

4. Lot No. ____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, David E. Erickson, in a field survey on August 18, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

This corner not set in original government survey of 1825.

Unrecorded survey by T. VanGleson - LS #24621, dated 11-17-80 shows A-8 to be 1.58' South of M-8.

In 1989, R.L. Enger - LS #28409, recorded the corner as "Established point for corner mid-distance between NW and SW corner of Section 19 and on the East boundary of T1S, R1E. Corner point is 1.46' South of M-8, T1S, R1E. Set 1/2" bar and cap "LS #28409" to monument corner point." and recorded five witnesses: "192° NAZ, 164.9', Nail and shiner in East side of 15" Walnut; 220° NAZ, 36.6', Nail and shiner in East side of 15" Walnut; 285° NAZ, 30.7', Nail and shiner in East side of 12" Walnut; 91° NAZ, 164.2', Nail and shiner in South side of 18" Cherry; 73° NAZ, 30.3', Nail and tag in NW side of Fence Corner Post" per Land Corner Recordation Certificate (LCRC) recorded in Liber 4, Page 137.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron established by Enger at road surface. Iron is on Town Line. Accepted found iron as established by Enger as best available evidence of corner position. Corner is not at midpoint due to change (remonumentation) of corner A-9.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Harrison monument with cap stamped "#29245".

N 66° E	Set nail and tag #29245, Northwest side fence post	30.44'
S 35° W	Set nail and tag #29245, East side 22" walnut	46.49'
N 78° W	Set nail and tag #29245, North side 17" Walnut	30.67'
N 17° W	Set nail and tag #29245, Northeast side 6" Hickory	89.47'
North	M-8, T1S, R1E (Harrison monument)	1.40'
N 88° W	County Surveyor sign post	16.9'
Northerly	A-7, T1S-R1E (Harrison Monument)	2656.23'
Southerly	A-9, T1S-R1E/M-9, T1S-R1E (Concrete monument)	2657.60'

NOTE: Bearings are magnetic

STATE OF MICHIGAN
DAVID E. ERICKSON
Land Surveyor
No. 29245
LICENSED LAND SURVEYOR

Signed by David E. Erickson Date 3-11-98

Surveyor's Michigan License No. 29245

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975
REVISED JAN. 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993