07

Lansing ~ Forestry

KALKASKA Co.

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N. S., R. 6 E. W.	G-2; G-3; H-3
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 2-1 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__ , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

G-2 B. Continued: Accepted Exist. Dept. Mon as established by M.Schaaf (Deceased Dept. Surveyor) in Aug. 1939. Schaaf notes indicate he reestablished the Govt corner from US evidence, Wit. stp & wit. stp site & line tree site, and his notes show Cons.Power Co. corner (Fargo) as bearing N80 E, 42 links. Fargo notes indicate they set a pipe at position of fd. stk. & one US Wit in 1913. We recovered Fargo's pipe,buried,and it does not appear to have been used in recent years. The Dept.Mon & Ced. Gd. Post is clearly marked and obvious and has been used by several R.L.S. (Sageman,Autry,Erickson,Finnerty, etc.) for control for platting & Sec. Subdn in Sec.4. Dept MOn was therefore reluctantly accepted as controlling corner since it seems to have been used & accepted by Previous RLS

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-3 Dept. Monument at corner position as recovered by M. Schaaf, which equals "Fargo' corner 1913. Schaaf found U.S. evidence in 1939.

H-3 Reestablished corner by single proportion.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-2			G-3			H-3		
Recovered Exist. Dept. Mon w/Cedar Guard Post			Recovered Exist.Dept.Mon w/Cedar Guard Post			Set DNR Mon w/Cedar Gd Post		
12" Maple	N19W	27.5'	9" Cedar	N38W	22.0'	14" Cedar	S4 W	12.0'
9" Tamarack	N15E	95.1'	14" Hemlock	N 3E	27.6'	10" Cedar	N75E	23.4'
16" Oak	S55E	119.4'	6" Cedar	S28E	4.7'	10" Cedar	N30W	14.2'
Fd 3/4" Fargo pipe buried	N79°38'E	28.1'	30" W.Pine stp	S80W	7.4'	12" Cedar	N87W	25.5'

SIGNED BY Carl F. Roser DATE 6-15-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. ML M736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS