LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. S., R. 8 E. W.	I-4;I-5;I-6
2. PROPERTY CONTROLLING IN SECTION 10	T. 26 N. S., R. 8 E. W.	7
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 18, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and of subsequent restoration

C. (contined) 7

Fd. 1/2" re-rod w/RLS Cap. #14102
& added Ced.Post w/Loc. Tag.

5" W.Pine	N02°W	42.4
11" Cherry	S19°W	102.4
10" W.Pine	S58°W	152.3

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-4 Recovered 1/2" rod by RLS, J. Wilcox who restored corner close to W.S.Merrill position of 1909 & 1911. A stone, in error, by MSHD, is S04°E, 103'. Also, Fd. 1" pipe, N04°E,94.62.

I-5 Fd.1-1/4" pipe, with rocks; fits old county surveys of record.

I-6 Fd. 1/2" rod w/RLS Cap, J.Fletcher, who restored corner from W.S. Merrill survey.

7 Fd. 1/2" re-rod, RLS J. Wilcox who established 1/8 corner by single proportion.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-4

Fd. 1/2" Rod w/RLS Cap
& Set Ced.Post w/Loc.Tag.

8" Tamarack	S38°W	33.7
Wilcox Wit.--Side Nails		
4" Balsam	S28°W	33.39
3" Balsam	N62°W	37.33
5" Map.(in clump)	N30°E	21.42

I-5

Fd. 1 1/4 Pipe & Set Cedar Post w/Loc. Tag

14" Maple	S63°W	45.35
13" Maple	N54°W	43.30
Fd.1/2"Re-rod w/Cap #19830W.		33.06
Ctr.E-W trail rd.	Due S.	10'±
Ctr.trail rd. to S.	Due E	25'±

I-6

Fd. 1/2" Rod w/RLS Cap Buried 0.8'

7" Hemlock	S53°E	34.88
18" Balsam	S33°E	48.92
28" Maple	S75°W	22.41
31" Elm	N25°W	49.72
3/8" re-rod w/RLS Cap #19830 W.		33'
Set Ced.Post w/Loc.Tag. E		16.5'

SIGNED BY Carl F Roser 9-18-78 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR
(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

BOARDMAN TOWNSHIP
KALKASKA COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET