LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N. S., R. 12 E. W.	F-9; F-10
2. PROPERTY CONTROLLING IN SECTION 28	,T. 18 N. S., R. 12 E. W.	3;
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 22, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and subsequent restoration~~

B. (continued) cannot properly be restored by "Mary Wills Sub'n". However, since "Mary Wills Sub'n." is of long standing acceptance its boundaries were accepted.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-9 Re-estab. 1/4 Cor. equidistant & on line between Sec. corners to E & W. Also see B, item 2, Sec. 28, Code 5.

F-10 Fd. and accepted Ir. for center of Sec. 28; fits Blass wits.

3 Found 3/4" iron rod in ctr. of N-S trail, being the NW Cor. of S 1/2-NW 1/4 of Sec. 28, per un-recorded sec. sub'n., "Mary Wells Sub-division", as surveyed & layed out by R.L.S., Geo.Blass, in 1941. "Mary Wills Sub'n" is not recorded and was intended to be a break down of part of Sec's 28&29 into 5 Ac± parcels, based on proper Sec. Sub'n. This did not turn out to be true in Sec. 28 as the NW Cor. of Sec. 28 was never located and (cont.)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-9	F-10	3
Set DNR Mon.& Ced.Post	Fd. iron rod, raised	Fd. 3/4" iron rod in ctr.
5" Elm (Alive) N30°W 45.4	w/1"X10" pipe	N-S trail
4" Spruce S65°E 49.9	17" B.Oak N60°E 50.63	5" W.Pine N42°E 26.6
5" Elm (Alive) S40°E 19.2	13" B.Oak S05°E 28.62	6" W.Pine S45°E 13.1
Cor. is on end of rand from S.	Set ced.post w/loc.tag	Set Ced.Post w/loc.tag
	Due S 33'	Due E 33'
	Ctr E-W dirt rd.	
	Due N 2'	

SIGNED BY Carl F. Roser 5-15-78 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

CHERRY VALLEY TOWNSHIP
LAKE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET