MAR 2 9 1999

SECTION

1998 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD
98 DEC 22 PM 3:49
Melissa DeVaugh
REGISTER OF DEEDS
LAPEER COUNTY, MICHIGAN

429

Register of Deeds Stamp & File Number

For corners in: **DEERFIELD TWP.**

LAPEER (County) Located In:

			Corner Code #
1. Public Land Survey		T 09N R 10E	K-1
		T___ R___	
		T___ R___	
		T___ R___	
2. Property Controlling	S___	T___ R___	
in Section	S___	T___ R___	
3. Miscellaneous	S___	T___ R___	
Property in Sec.	S___	T___ R___	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, JONATHAN M. FIELD, in a field survey on JUNE 30 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
1834 GLO; BURNHAM , D.S.; INTERSECTED N BNDY 46LKS E; BEECH 12 S24W 46 LKS, BEECH 14 S58E 70 LKS.
1906 SICKLESTEEL, C.S.; SURVEY SEC. 1, T9N-R10E; PG.2-3; NO OBJECT STATED; NO WITS GIVEN
1906 SICKLESTEEL, C.S.; SURVEY SEC. 2, T9N-R10E; PG.4-5; STAKE; PINE 44 S60W 9LKS., PINE 36 S34E 133LKS.
1989 GRAVLIN, P.S.#23510; SURVEY L.008, PG.202; FND. P.K. NAIL; N60°W 123.52' 24" MAPLE, S40°E 50.75' COR POST, S45°W 35.45' N. FACE ST. SIGN POST
1989 GRAVLIN, P.S.#23510; SURVEY L.008, PG.295-7; FND. PIPE; SAME WITS AS 1989 SURVEY ABOVE
1989 GRAVLIN, P.S.#23510; LCRC L.004, PG.277; FND. P.K. NAIL; SAME WITS AS 1989 SURVEY ABOVE
1992 GRAVLIN, P.S.#23510; SURVEY L.009, PG.658-9; FND. PIPE; SAME WITS AS 1989 SURVEY ABOVE
1994 GRAVLIN, P.S.#23510; SURVEY L.010, PG.440; FND. PIPE; SAME WITS AS 1989 SURVEY ABOVE
1994 FIELD, P.S.#37276; LCRC L.005, PG.184 (1994 REMON); FND. 5/8" ROD IN MON BOX 11.31' EAST OF K-13 T10N-R10E
1997 GRAVLIN, P.S.#23510; SURVEY L.0012, PG.0095-6; FND. PIPE; SAME WITS AS 1989 SURVEY ABOVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1998 ROWE; FIELD, PS#37276; FND. 5/8" ROD IN MON. BOX RECOVERED 2 PREVIOUS WITNESSES WHICH INDICATE THAT FND. ROD IS IN SAME POSITION AS 1989 IRON CITED IN SECTION A ABOVE

K-1 TO APPARENT J-1	2644.80' (ROWE '98) 2642.37' (GRAVLIN '89)	K-1 TO K-13	30.36' (G.L.O.) 11.31' (ROWE '98)

ACCEPTED FND. ROD AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
K-1 SET STD. REMON CAP ON 5/8" FND. 5/8" ROD
WEST, 11.31' 1/2" ROD W/ LAPEER REMON CAP IN MON. BOX
S41°W, 33.85' CHIS. + ON TOP CENTER CONC. PILLAR
N11°E, 30.60' NAIL W/ FLAG. IN E. FACE 4" ASH
N47°E, 41.55' NAIL W/ FLAG. IN E. FACE 8" TWIN ASH
S13°W, 101.18' NAIL W/ FLAG. IN E. FACE 8" ELM

STATE OF MICHIGAN
JONATHAN M. FIELD
PROFESSIONAL SURVEYOR
No. 37276
LICENSED PROFESSIONAL SURVEYOR

DATE 10-13-98

Signed by Jonathan M Field Date 10-28-98

Surveyor's Michigan License No. 37276

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993