LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Alger Co. Two Corners.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 45 N. S., R. 8 E. W.	E-1 - E-11
2. PROPERTY CONTROLLING IN SECTION ____	,T. ____ N. S., R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ____	,T. ____ N. S., R. ____ E. W.	
4. LOT NO. ____ , RECORDED PLAT ____		
5. PRIVATE CLAIMS ____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 3-10-72 & 9-20 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

E-1 Sec. Cor. 4-5, on North Boundary of Township, set by Wm. A. Burt, D.S., 1840.
Bearings were:
Spruce 3", N38°E, 23 lks. and Spruce 4", N30°W, 14 lks.

E-11 Sec. Cor. 27-28-32-33, set by Wm. Ives, D.S. in 1849.
Bearings were:
Cedar 7", N55°W, 13 lks. and Cedar 10", S50°E, 20 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-1 Found old squared spruce tree. Position checks with river crossing to West.

E-11 Found old Cedar post with blazes and a signature (Slater 1936). Position checks with stream to South. Found several old cedars but none identified as original.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminium cap at both corners.

E-1 New Bearings:
16" W. Pine, S46°E, 14.1' and 12" B. Spruce, N17°W, 15.5'

E-11 New Bearings:
9" Cedar, N77°E, 14.2' and 9" Cedar, S17°E, 21.7'

SIGNED BY Billy D. Buckler DATE 9-26-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ CHIEF OF SURVEY PARTY DATE ____

APPROVED AND SIGNED BY ____ MICHIGAN REGISTERED LAND SURVEYOR DATE ____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. ____

Form No. MLM735
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS