LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co. Two Corners

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 46 N. ~~S.~~, R. 9 ~~E.~~ W.	K-7 G-5
2. PROPERTY CONTROLLING IN SECTION ____	T. ____ N. S., R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ____	T. ____ N. S., R. ____ E. W.	

4. LOT NO. ____, RECORDED PLAT ____

5. PRIVATE CLAIMS ____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 8/31 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

K-7 Sec. Cor. 13-14-23-24, set by Harvey Mellen, D.S., 1850.
Bearings were:
Tam. 7" N64°E 74 LKS and Tam. 3" S35°W 27 LKS

G-5 Sec. Cor. 9-10-15-16, set by Harvey Mellen, D.S., 1850.
Bearings were:
Cedar 8" N7°E 21 LKS and Tam. 10" S33°W 33 LKS

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-7 Corner re-established on a straight line between corners, 1 mile East and 2 miles West, to conform with the procedure used in original survey.

G-5 Corner re-established midway and on line bet. corners, ½ mile North and ½ mile South. Found no evidence of original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminum cap at both corners.

K-7 Key Bearings:
6" B. Spruce N75°E 36.1' and 6" B. Spruce N15°W 46.0'

G-5 Key Bearings:
10" Soft Maple S60°E 44.9' and 8" B. Spruce N5°E 10.0'

SIGNED BY Billy D. Buckler DATE 11/27/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8587 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ CHIEF OF SURVEY PARTY DATE ____

APPROVED AND SIGNED BY ____ MICHIGAN REGISTERED LAND SURVEYOR DATE ____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. MLM735
DOUBLEDAY BROS. & CO. KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS