LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co. 3 Corners

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 49 N. ~~S.~~, R. 8 ~~E.~~ W.	B-4, B-5, B-6
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 6/6, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B-4 Center Corner, Section 7.

B-5 Quarter Corner between Section's 7-18.

B-6 Center Corner, Section 18.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

B-4 Moved this corner monument to correct position. Corner was placed erroniously 5-9-75. Moved 19.66' West of former monument.

B-5 Moved this corner monument to correct position. Corner was placed erroniously by myself 5-9-75. Moved 39.33' West and 74.42' South of former monument.

B-6 Corner placed at intersection of lines connectting opposite quarter corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at all corners.

B-4 New Bearings: 12" W. Pine, N5°E, 18.0' and 8" R. Pine, S15°E, 18.5'

B-5 New Bearings: 24" Hemlock, N32°E, 63.0' and 8" Soft Maple, N82°W, 21.2'

B-6 Bearings: 12" W. Pine, S30°E, 50.0' and 8" Soft Maple, N86°W, 21.0'

SIGNED BY Billy D. Buckler DATE 9-8-78

Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

STATE OF MICHIGAN BILLY D. BUCKLER LAND SURVEYOR NO. 8887 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975