LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co. 2 Corners.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 42 N. S., R. 7 E. W.	J-1
2. PROPERTY CONTROLLING IN SECTION 2	T. 42 N. S., R. 7 E. W.	2
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 5-12, 19 82, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

-1 1/4 Cor. on north side of sec. 2. Wood Post, 6" Fir, N75°E, 23lks. & 6" Beech, N89°W, 20 lks. Re-set by Billy D. Buckler in 1964. D.N.R. Mont. N.B.T's. 9" Y. Birch, S8°E, 75 lks. and 9" H. Maple, S41°W, 72½ lks.
East 1/16 cor. on north side of sec. 2. Set by Billy D. Buckler in 1964. D.N.R. Mont. B.T.'s 6" H. Maple, S62°W, 73½ lks. and 9" Y. Birch, S12°E, 62 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

-1 Billy D. Buckler's record shows this corner to be set M,P.O.L. between the N.E. and N.W. sec. cors. of sec. 2. We found his mon. and N.B.T's but the mon. was actually set 49.75' East of M.P.O.L. betw. sec. cors. We re-set his monument to the M.P.O.L. position and took N.B.T.'s as shown in "C".
Billy D. Bucklers record shows this cor. to be set M.P.O.L. betw. the N¼ cor. and the NE sec. cor. of sec. 2. We found this mon. and NBTS, but the mon was actually set 25.2' east of the M.P.O.L. position. We re-set his mon. to the M.P.O.L. position and took NBTS as shown in "C".

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

-1 D.N.R. Monument. New Bearings:

12" H. Maple,	S23°E,	39.6'
20" Beech,	S23°W,	4.5'
10" H. Maple,	N53°E,	10.8'
10" Beech,	N8°E,	14.6'

2 D.N.R. Monument. Bearings:

6" H. Maple,	N43°E,	5.1'
8" Beech,	N14°W,	14.1'
18" Hemlock,	S25°W,	38.2'
12" Y. Birch,	S38°E,	52.4'

SIGNED BY David B. Babbitt DATE 8-3-82
David B. Babbitt

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558 (SEAL)

FOR STATE AND UNITED STATES AGENCIES: