LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co. 4 Corners.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 44 N. S., R. 7 E. W.	G-5, G-6
2. PROPERTY CONTROLLING IN SECTION 15	T. 44 N. S., R. 7 E. W.	3-Sec.15, 8-Sec.15
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 4-22 & 4-29, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-5 Sec. Cor. 9-10-15-16, set by H. Brevoort Jr., D.S. in 1845. Bearings were: Sugar 12", N36°W, 22 lks. and Beech 12", S61°E, 56 lks.

G-6 1/4 Cor. bet. Sec's. 15-16, set by H. Brevoort Jr., D.S. in 1845. Bearings were: Birch 8", S54°W, 08 lks. and Cedar 6", N22°E, 11 lks.

3-Sec.15 North 1/16 Corner on West side of Section 15.

8-Sec.15 West 1/16 Corner of Section 15.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-5 Re-witnessed corner as monumented by myself in 1957. Found 1957 witnesses both grown over. Original witness tree, Sugar 12", N36°W, 22 lks., still green. 1" pipe with brass cap still in place.

G-6 Corner re-established midway and on line bet. two Sec. Cors. Found numerous cedar remains but none recognized as a witness. Fragmented limestone covers the area.

3-Sec.15 Placed cor. midway bet. 1/4 cor. to South and original sec. cor. to North. Found numerous old blazes to North and South.

8-Sec.16 Established corner midway and on line bet. 1/4 cor. to West and computed center of sec. 15.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-5 This record will supplement the record dated 6-10-57. New Bearings: 12" H. Maple, N88°W, 44.4' & 8" H. Maple, S12°E, 23.4'.

Placed 1" pipe with 4" alum. cap at remaining corners. Bearings are:

G-6 No witnesses available.

3-Sec.15 12" R. Maple, N30°W, 1.6' & 10" H. Maple, S57°W, 44.8' & 10" H. Maple, S60°E, 29.3'

8-Sec.15 10" R. Maple, N4°W, 9.3' & 7" H. Maple, S84°E, 32.5'.

STATE OF MICHIGAN BILLY D. BUCKLER LAND SURVEYOR NO. 8887 REGISTERED LAND SURVEYOR

SIGNED BY Billy D. Buckler DATE 8-7-81

Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

USE SPACE SKETCH ON BACK OR ATTACHED SHEET