SURVEY &
REMONUMENTATION

MAR 1 6 1998

SECTION

LIBER -- 4 PAGE 130

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MASON
(County)

	Located In:	Corner Code #
1. Public Land Survey	T 18 N R 16W	L - 13
	T ___ R ___	
	T ___ R ___	
	T ___ R ___	
2. Property Controlling	S ___ T ___ R ___	
in Section	S ___ T ___ R ___	
3. Miscellaneous	S ___ T ___ R ___	
Property in Sec.	S ___ T ___ R ___	

MASON COUNTY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____.
5. Private Claims _____.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Sammy S. Barnett, in a field survey on Sept.12th 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L -13 South one-quarter corner, section 36 T18N, R16W
1838 GLO survey by Mullett & Brookfield
Set post

1 Beech 14" N54W 4 lks (2.64')
2 Beech 12" N08E 8 lks (5.28')

1994 survey by K. Ross, set 1/2" iron rod
3 W. Oak 36" N60E 9.39'
4 W. Oak 16" N40E 12.93'
5 Cherry 6" N27W 28.24'
6 TW Cherry S52W 89.90'
7 1/2" IR., closing corner E. 8.25'
E-W trail road is South 50'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L -13 South one-quarter corner, section 36 T18N, R16W

On Sept. 12th 1997, I found the 1/2" iron rod set by K. Ross, the condition of the witnesses are as follows.
1 Gone # 2 Gone # 3 Found # 4 Found # 5 Found # 6 Found # 7 Found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L -13 South one-quarter corner, section 36 T18N, R16W

On Sept 12th, 1997, I replaced the found 1/2" iron rod with a Standard Mason County Monument and accepted this location as a careful and faithful re-establishment of the position of the original corner, and took the following witnesses.

8 W. Oak 36" N60E 9.39' 60d spike in NE side (#3)
9 W. Oak 16" N40E 12.93' 60d spike in SE side (# 4)
10 Cherry 6" N27W 28.25' 60d spike in W. side (# 5)
11 Tw cherry 8" S52W 89.92' 60d spike in NW side (# 6)
12 Standard Mason County Monument East 8.25' (# 7)

STATE OF MICHIGAN
SAMMY S. BARNETT
PROFESSIONAL SURVEYOR
No. 16923
LICENSED PROFESSIONAL SURVEYOR

Signed by Sammy S Barnett Date 11-4-97

Surveyor's Michigan License No. P S # 16923

Peer Group Reviewed and Approved
Date: Oct. 2, 1997
Kenneth L. Ross
Mason County Surveyor

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

LIBER - 4 PAGE 130