SURVEY &
REMONUMENTATION

JAN 23 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

FILED
AT 9:34 O'CLOCK A M
AUG 17 2000
MARGARET KOLASKI ELLIOTT
MASON COUNTY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners In:	Located In:	Corner Code #
Mason County		
. Public Land Survey	T 18N R 17W	A-2
	T 18N R 18W	M-2 ✓
	T R	
	T R	
. Property Controlling	S T R	
in Section	S T R	
. Miscellaneous	S T R	
Property in Sec.	S T R	

. Lot No. _____, Recorded Plat _____
. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

. Kenneth L. Ross in a field survey on June 14, 2000, Do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970,the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

4 corner common to section 6, T18N, R17W, and Section 1, T18N, R18W

A. Description of original monument and accessories and/or subsequent restoration:

Mullett & Brookfield 1838
Set ¼ Sec. post
Beech 14 S65W 20 lks. (13.20') #1
Beech 14 N29W 26 lks. (17.16') #2

Ross PLS 17634 1977 Set 1" pipe
by single proportionate measurement between A-1 & A-3 of T18N, R17W
2.6 ft. North of fence intersection. Fence to north and East.
18" Hemlock S25W 19.95' #3
14" W. Pine S10E 48.31' #4
12" Maple S60E 31.76' #5
12" Tw. Maple N30W 30.81' #6

This corner position has been used in several boundary surveys by Ross and Nordlund.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

found a 1" X 18" pipe on a N-S fence and a fence to the East.

Condition of the accessories: 1 and 2 are gone, 3, 4, 5, and 6 are in good condition.

I found nothing to dispute the location of this corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replace the 1" pipe with a Harrison Monument stamped "Mason County Monument 17634". I accepted this as a careful and faithful reestablishment of the position of the original corner.

2.6 ft. North of fence intersection. Fence to north and East.
20" Hemlock S25W 19.95' #3
16" W. Pine S10E 48.31' #4
14" Maple S60E 31.76' #5
15" Tw. Maple N30W 30.81' #6

STATE OF MICHIGAN
KENNETH L. ROSS
LAND
SURVEYOR
No.
17634
REGISTERED LAND SURVEYOR

Signed by _____ Date 8-10-2000
Surveyor's Michigan License No. 17634

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

Approved by Peer Review Group on 8-10-2000
Kenneth L. Ross, County Representative _____