SURVEY & REMONUMENTATION

DEC 2 9 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

FILED
10 O'CLOCK 31 A.M.

Register of Deeds Stamp & File Number

For corners in MASON (County)

	Located In:	Corner Code #
1. Public Land Survey	T 19N R 16W	C-3
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6		18	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11													
12		31	32	33	34	35	36						
13													

I, Kenneth L. Ross, in a field survey on June 22 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
C-3 Section Corner for Sections 5, 6, 7, and 8, T19N R16W.

1838, Slyvester Sibley, G.L.O.
Set Wood Post
#1 Black Ash 12" N 71 E 17 lks.(11.22')
#2 Birch 10" S 36 W 9 lks.(5.94')

1893, J. W. Griswold, Mason Co. Surveyor
Set post from Gov't witness trees,
Gives a distance of 39.90 chs.(2633.40') from the East 1/4 cor., Sec. 7 and 39.50 chs.(2607.00') to the North 1/4 cor. Sec. 7, 19-16.
(Book 1, page 264 & 265)

1985, Gordon Bonney, RLS #12016 (liber 3, pg. 4)
Set a 1/2" Re-Rod, with RLS cap in C-L line of Road, in line with old fence to the South and tree-line to the North.
#3 Maple 36" S 50 W 44.34'
#4 Maple 8" S 48 W 43.70'
#5 Maple 8" S 05 W 31.31'

1997, Kenneth Ross, RLS #17634 (file 95390s.)
Found and excepted 1/2" Re-Rod by Bonney.
#6 Maple 8" S 05 W 31.65'
#7 Ash 6" N 21 W 19.91'
#8 Maple Clump 10" S 75 W 57.67'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
C-3 Section Corner for Sections 5, 6, 7, and 8, T19N R16W.

On June 22, 1998, I found the 1/2" Re-Rod set by Bonney, I found no evidence to dispute this location for the corner.

Condition of record witnesses are as follows; #1 Gone #2 Gone #3 Did not locate

#4 Found in good condition #5 Found in good condition #6 Same as #5 #7 Found dead

#8 Found in good condition

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
C-3 Section Corner for Sections 5, 6, 7, and 8, T19N R16W.

I replaced 1/2" re-rod by Bonney, in the exact location, with a Harrison cast iron monument, stamped MASON COUNTY MONUMENT, placed 0.5 feet below the road surface. This corner is accepted as a careful and faithful re-establishment of the position of the original corner.

xt. "BT" #4 Maple 9" S 48 W 43.72' (60d spike in NW side of tree)
xt. "BT" #5 Maple 9" S 05 W 31.65' (60d spike in east side of tree)
xt. "BT" #8 Maple Clump 12"-14"-15" S 75 W 57.67' (60d spike in north side of tree)
ew "BT" #9 Maple 6" N 50 W 33.55' (set 60d spike in SW side of tree)

STATE OF MICHIGAN
KENNETH L. ROSS
LAND SURVEYOR
NO. 17634
REGISTERED LAND SURVEYOR

igned by Kenneth L. Ross Date Sept. 8, 1998

urveyor's Michigan License No. 17634

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

LIBER --4 PAGE 219

Date: 9-8-98