SURVEY &
REMONUMENTATION

MAR 1 6 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

FILED
AT 4:05 O'CLOCK P M
NOV 2 0 1997
MARY GOLDEN KOLASKI
MASON COUNTY
REGISTER OF DEEDS
Register of Deeds Stamp & File Number

For corners in
Mason
(County)

	Located In:	Corner Code #
1. Public Land Survey	T 20N R 16W	D-13
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous S	T R	
Property in Sec.	S T R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Richard L. Hays, in a field survey on August 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-13 SOUTH QUARTER OF SECTION 32, T20N-R16W
1839: G.L.O Survey

10" Black Ash	N-17°-W	34 Lks	(1)
10" Black Ash	N-35°-E	20 lks	(2)

1981:Ross Survey R.L.S. #17634 Act 132, Liber 277, Page 457

Set 1/2" Re-Rod

Power Pole	S-80°-W	175.60'	(3)
Telephone Box	N-80°-W	158.90'	(4)
10" Cl. Maples	S-45°-E	60.35'	(5)
1/2" Iron Rod	East	23.76'	(6)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-13 SOUTH QUARTER OF SECTION 32, T20N-R16W
August 1997: Found 1/2" Re-Rod. Condition of the Witnesses are as follows:

10" Black Ash	N-17°-W	34 Lks	(1)	(GONE)
10" Black Ash	N-35°-E	20 lks	(2)	(GONE)
Power Pole	S-80°-W	175.60'	(3)	(FOUND)
Telephone Box	N-80°-W	158.90'	(4)	(FOUND)
10" Cl. Maples	S-45°-E	60.35'	(5)	(FOUND)
1/2" Iron Rod	East	23.76'	(6)	(FOUND)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-13 SOUTH QUARTER OF SECTION 32, T20N-R16W
August 1997: Replace the 1/2" Re-Rod with a Standard Mason County Monument, and is accepted as the best available evidence of the position of the Original Corner.

Spike SW side	10" Cl. Maples	S-45°-E	59.82'	(5)
Spike W side	6" Maple	S-13°-E	47.52'	
	3/8" Re-Rod	N-05°-E	15.99'	
	3/8" Re-Rod	N-68°-E	52.22'	
	1/2" Iron Rod	East	23.78'	(Closing Corner)
	Telephone Box	N-80°-W	158.90'	
Spike N side	Power Pole	S-88°-W	175.60'	

Signed by Richard Hays Date 11/6/97

Surveyor's Michigan License No. 25847

Peer Group Reviewed and Approved
Date: Nov. 2, 1997
Kevin D. Rice

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1991

LIBER 4 PAGE 187