DEC 19 2000

SECTION

MONTCALM COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Montcalm (County)

Located In: Eureka Township

Corner Code #

1. Public Land Survey Sec 7 T 9 N R 8 W — A-4, W 1/4
2. Property Controlling in Section S___ T___ R___
3. Miscellaneous Property in Sec. S___ T___ R___

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED
27 DEC 1999 9:38:05 AM
LORI A. WILSON
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William Tingley a field survey on _____, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

May 28, 1837, Noah Brookfield, Deputy Surveyor, GLO Notes
Set Post
White Oak 10" S20°W 1.56 chains
Yellow Oak 9" N60°W 1.70 chains
May 1963, Michigan State Highway Department
Found 7" x 4" point stone beside old wood stake 1" x 2", raised with axle shaft
Oak 30" N68°E 62.12 feet
Twin Oak 15" S70°E 57.85 feet
Telephone Pole Due West 82.75 feet
July 1983, Burt Wickham, #17639, Liber 580, Page 1222, Recorded Survey
Found 2" Solid Rod
8 foot south of Centerline "X"
Set P.K. Nail in Northside Wood Post West 29.0 feet
Telephone Box Northwest 54.90 feet
Street Sign Southeast 47.75 feet
1986, J. Bueche, #13027, LCRC 4534 Kent County Records
Found pointed Stone and Axle Shaft on Centerline Gravel Road N-S and E. Replaced with Kent County Monument
Kent County Remonumentation Tag and Nail Northside 4" x 4" Wood Sign Post S85°W 18.18 feet
Telephone Box N40°W 48.88 feet (capped iron, South)
Capped Iron 2 Feet South of Peach Tree S60°W 76.90 feet
Capped Iron 2 Feet South of Peach Tree S40°W 104.56 feet
Capped Iron 2 Feet South of Apple Tree S45°E 77.13 feet
Capped Iron 2 feet North of Apple Tree S65°E 88.14 feet
1994, J. Glaza, #40166, LCRC #7257, Kent county Records
Kent County Remonumentation Tag and Nail Northside 4" x 4" Wood Sign Post S85°W 18.18 feet
Capped Iron 1 foot South Michigan Bell Telephone Box N40°W 48.92 feet
Capped Iron 2 Feet South of Apple Tree S45°E 77.13 feet
Capped Iron 2 feet North of Apple Tree S65°E 88.14 feet
Axle Shaft S10°E 6.12 feet

ACCEPTED BY THE MONTCALM COUNTY SURVEY FEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 11/23/99

William Tingley, PS, Chairman

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Kent County Monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Kent County Monument.
Capped Iron is South Michigan Bell Telephone Box N40°W 48.92 feet
Capped Iron 2 Feet South of Apple Tree S45°E 77.13 feet
Capped Iron 2 feet North of Apple Tree S65°E 88.14 feet
Axle Shaft S10°E 6.12 feet

MICHIGAN WILLIAM G. TINGLEY PROFESSIONAL SURVEYOR NO. 30104 PROFESSIONAL SURVEYOR

This corner is accepted as a careful and faithful perpetuation of the position or the original corner.

Signed by William G. Tingley Date 22 Dec, 1999

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

E4 192 1