DEC 19 2000

SECTION

MONTCALM COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Montcalm (County) | Located in: Eureka Township | Corner Code #

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED
7 NOV 2000 9:12:57 AM
LORI A. WILSON
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey	Sec 18	T 09N	R 08W	A-07 SW Corner
		T 09	R 09	M-07 KENT
		T	R	
		T	R	
2. Property Controlling	S	T	R	
in Section	S	T	R	
3. Miscellaneous	S	T	R	
Property in Sec.	S	T	R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6		18	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11													
12		31	32	33	34	35	36						
13													

I, William Tingley a field survey on May 8, 2000 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. **May 28, 1837, Noah Brookfield, Deputy Surveyor, GLO Notes**
   Set Post

Bur Oak	10"	N28°W	18 links
White Oak	18"	S60°W	53 links

2. **1978, W. Byl, #23502, LCRC #3589, Kent County, (M-7)**
   Set 1/2" x 24" iron with cap on occupation East and West, and in Centerline of North-South Gravel Road.

Nail in face	10" Oak	East	14.06 feet
Nail in face	8" Oak	West	14.38 feet
Nail in face	20" Maple	Southwest	42.90 feet
Nail in face	10" Maple	South Southeast	64.45 feet
Nail in face	12" Twin Oak	Northwest	42.42 feet

ACCEPTED BY THE MONTCALM COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 10/11/00

WGT

William Tingley, PS, Chairman

3. **September, 1987, Kevin Roosien, #31604, Liber 617, Page 97, recorded survey**
   1/2" Solid Rod Verified previous record
4. **1984, W. Byl, LCRC #3942, Kent County**
   Found per LCRC 3589 witnesses. Found 1/2" rod 33 feet West. Fits data from Williams & Works 1913 survey - 2619 feet North of East 1/4 Corner. See sketch of data. Set 4" x 30" Kent County Monument in place of iron.

Nail and Tag	Southside 12" Oak	S85°E	14.51 feet
Nail and Tag	Westside 15" Maple	S15°E	64.93 feet
Nail and Tag	Eastside 24" Maple	S20°W	80.66 feet
Nail and Tag	Northside 12" Oak	N85°W	14.80 feet
Nail and Tag	Eastside 10" Oak	N25°W	30.40 feet

STATE OF MICHIGAN
WILLIAM G. TINGLEY
PROFESSIONAL SURVEYOR
NO. 30104
LICENSED PROFESSIONAL SURVEYOR

5. **1994, J. Glaza, LCRC 7260**
   Found Kent County Monument (broken). Replaced with standard Kent County Monument.

Nail and Tag in Northwest side 4" Twin Oaks	N60°E	39.92 feet
Nail and Tag in Southside 6" Oak	S80°W	32.07 feet
Nail and Tag in Northside 10" Oak	N72°W	32.77 feet
Nail and Tag in Westside Power Pole	S10°W	101.43 feet

6. **March 26, 1999, Randy Kolehouse # 25854, Kent County Remon LCRC # 11670**
   Found Standard Kent County Monument on the C/L of Montcalm Avenue (gravel) running north and south on line of a tree row and fence line running east and west per LCRC # 7260. Monument set by Byl was replaced by Glaza & Associates

Nail/KC remon tag NW/S tw oak 4"	N60°E	39.94 feet
Nail/KC remon tag S/S oak 6"	S80°W	32.07 feet
Nail/KC remon tag N/S oak 10"	N72°W	32.75 feet
Nail/KC remon tag W/S power pole	S10°W	101.40 feet
C/L N-S gravel road		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Searched the apparent location of the corner. Found Kent Co. Harrison monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Kent Co. Mon.

Fnd N/T NW/S 7" Twin Oak	N60°E	39.92 feet
Fnd N/T S/S 10" Oak	S80°W	32.07 feet
Fnd N/T N/S 13" Oak	N72°W	32.77 feet
Fnd N/T W/S P.P.	S10°W	101.43 feet

E4 295 1

LIBER 4 PAGE 295

Bearings given are magnetic. This corner is accepted as the best available evidence of the position of the original corner.

Signed by William Tingley Date 10/11/00

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993