SURVEY & REMONUMENTATION

1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Montcalm County Remonumentation Program

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED

21 DEC 93 3:11 P.M.

VIRGINIA L. KNEPPER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in Montcalm (County)

	Located In:	Corner Code #
1. Public Land Survey	Sec. 34 T 11 R 7	G-13, SW Cor
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William Tingley a field survey on October 11, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

December 9, 1836, Noah Brookfield, Deputy Surveyor from GLO Notes
Set Post Corners Sections 33 and 34 South Boundary
Beech 10" N57°E 22 links
Pine 18" N36°W 28 links
1884, H.M. Caulkin, County Surveyor from Surveyor Notes of Montcalm County Register of Deeds
Found Bearing Tree
Pine N36°W 28 links with marks plain
Set fire clay mon and blacksmith cinders
New Bearing Tree Pine Stump 22" N56-1/2W 70 links
September 13, 1909, J. E. Youdan, County Surveyor from Field Book 11-7 Page 72 and 73
Found Fire Clay mon
No New Bearing Trees given

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found P.K. masonry nail over 1/2" iron 1.8' below road surface. Dug 3.3' below surface found pieces of fire clay mon and black cinder.

Accepted 1/2" Iron as Corner.

SURVEY & REMONUMENTATION

1993

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set remonumentation corner and mon box over iron.
Nail and Tag East Side Power Pole S5°W 33.13'
Nail and Tag East side Power Pole N36°W 68.71'
Nail and Tag Public Access Sign S75°E 65.25'
Nail and Tag Public Access Sign S75°E 65.25'
North 1/4 Corner Section 5T10N R7W East 72.8'

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

STATE OF MICHIGAN
WILLIAM G. TINGLEY
LAND SURVEYOR
NO. 30104
REGISTERED LAND SURVEYOR

Signed by William Tingley Date November 23, 1993

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

LIBER 3 PAGE 78