DEC 19 2000

SECTION

MONTCALM COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Montcalm (County) | Located In: Maple Valley Township | Corner Code #

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED
7 NOV 2000 9:12:57 AM
LORI R. WILSON
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey Sec. 32 T 11 N R 09 W D-13
   T ____ R ____
   T ____ R ____
   T ____ R ____
2. Property Controlling S ____ T ____ R ____
   in Section S ____ T ____ R ____
3. Miscellaneous S ____ T ____ R ____
   Property in Sec. S ____ T ____ R ____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William G. Tingley, in a field survey on April 28, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

ACCEPTED BY THE MONTCALM COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 8/09/00

WGT

William Tingley, PS, Chairman

A. Description of original monument and accessories and/or subsequent restoration:

1. **December 11, 1836, Noah Brookfield, Deputy Surveyor, GLO notes**
   West on south side Section 32, Beech 20" Quarter section post
2. **April 19, 1968, Montcalm Road Commission witness card file, Maple Valley # 165**
   South ¼ Section 32

Maple 18"	SW	63.50 feet
Power pole	NW	65.60 feet
Maple 20"	NW	71.00 feet
SE cor. well cover	NW	69.60 feet

3. **1989, William R. Byl, # 23502, Survey 22-Mile Road Right-of-Way for MI Bell Cable Placement field notes**
   Found iron pipe
   No witnesses given

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found 1" x 2" iron pipe inside 1¼" x 24" iron pipe 6" below road surface. Excavated to 2.5 feet and found no other evidence. Found the old witnesses indicated on Stevenson's note card.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set remonumentation pipe over 1¼" iron pipe.

Set N/T N/S maple 30"	S80°W	63.82 feet
Set N/T E/S maple 30"	N18°W	71.66 feet
Set N/T NE/S power pole	N34°W	65.68 feet
Center S/S flag pole	N51°W	64.95 feet
T110N-R09W C-01	East	167.44 feet

STATE OF MICHIGAN
WILLIAM G. TINGLEY
PROFESSIONAL SURVEYOR
NO. 30104
LICENSED PROFESSIONAL SURVEYOR

This corner is accepted as the best available evidence of the position of the original corner.

Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"

Signed by William G. Tingley Date 8/09/00

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

E4 388 I