SURVEY
REMONUMENTATION
SEP 1 2 1995
COMMISSION

Corner approved by Peer Group on _____, 1994

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Montcalm (County)

	Located In:			Corner Code #
1. Public Land Survey	Sec 9	T 11	R 6	G-3, NE CORNER
		T	R	
		T	R	
		T	R	
2. Property Controlling	S	T	R	
in Section	S	T	R	
3. Miscellaneous	S	T	R	
Property in Sec.	S	T	R	

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED

10 AUG 95 3:32 P.M.

VIRGINIA L. KNEPPER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William Tingley a field survey on July 5, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1837, John Milroy, Deputy Surveyor, GLO Notes
Set post
Pine 40" S81°E 25 links
Beech 21" S73°W 19 links
Nov. 20, 1905 J.F.Daoust, County Surveyor, County Records Book 2, page 174
Found tile, took New Bearing Trees
Pine stump 20" N36°W 50 links
Maple 6" N 20-3/4°E 108 links
Jan 19, 1909 J.F.Daoust, County Surveyor; Field Book 11-5, page 90
Found monument from bearing trees above.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found large angle iron on the Southwest side of a 0.30 foot round tile with concrete surrounded by rocks, 1.6 feet below the road surface.

ACCEPTED BY THE MONTCALM COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 19 Apr. 95

William G Tingley
William Tingley, PS, Chairman

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Remonumentation Corner and Monument Box over tile
Set Nail & Tag, Eastside 28" Maple N45°E 71.45 feet
Set Nail & Tag Eastside Telephone Pole S40°w 66.01 feet
Street Sign Post S40°W 45.51 feet
Located 5 feet North of Intersection North-South-East Paved Road

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William G Tingley Date 19 April, 1994

Surveyor's Michigan License No. 30104

STATE OF MICHIGAN
WILLIAM G. TINGLEY
PROFESSIONAL SURVEYOR
NO. 30104
LICENSED PROFESSIONAL SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 21, 1971
REVISED MAY 13, 1975
REVISED JAN., 1983
ADAPTED FOR CARD PROCESSING MARCH, 1993

LIBER 3 PAGE 193