LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 29 N., R. 3 E.	E-5
2. PROPERTY CONTROLLING IN SECTION 17	,T. 29 N., R. 3 E.	8; E-6/9; E-6/7
3. MISCELLANEOUS PROPERTY IN SECTION _____	,T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on August 21, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__ , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and/or subsequent restoration~~

C. (continued)

E-6/7
Set 2½' of 1" pipe
16" Cedar S60E 90.0'
6" Maple N14E 5.0'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-5 Found ½" rerod and point of old stake stubs of both OBTs in place with very plain faces, scribe marks still plain on northeast one. Southwest OBT is about 10 lks. farther out than record. DeLaMater W.P. witness south still living, but northeast one has been cut and stump is rotten.

8 Found concrete monument as established by Rouse.

E-6/9 Property Corner.

E-6/7 Property Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-5			8			E-6/9		
DNR Mon. beside E. gate post			Left ½" rerod in conc. mon.			Set 2½' of 1" pipe		
8" Maple	N73W	26.6'	in place			6" Poplar	S80W	4.6'
18" W. Pine	South	27.7'	7" W. Oak	N83W	26.2'	5" Poplar	S60E	4.4'
14" R.P. Stub	N40E	16.1'	8" Maple	N56W	17.3'	1" Balsam	S02E	32.5'
13" R.P. Stub	S55W	29.6'	(in clump)			1½" Balsam	S65W	18.7'

STATE OF MICHIGAN
KENNETH J. OSTLING
LAND SURVEYOR
No. 10068
REGISTERED LAND SURVEYOR
SEAL

SIGNED BY Kenneth J Ostling DATE 10-8-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ (CHIEF OF SURVEY PARTY) DATE _____

APPROVED AND SIGNED BY _____ (MICHIGAN REGISTERED LAND SURVEYOR) DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. ML M736
FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS