# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF–: | LOCATED IN–: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY | T. 31 N., R. 3 E. | H-9; I-9 |
| 2. PROPERTY CONTROLLING IN SECTION 27 | ,T. 31 N., R. 3 E. | 1; 2 |
| 3. MISCELLANEOUS PROPERTY IN SECTION | ,T. N. S., R. E. W. | |

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on August 2, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__ , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-9 Restored this corner at midpoint on line between section corners. Could not recover GFD corner or witnesses.

I-9 Found ½" bar in line with fences N-S, probably by DeLaMater in 1935 survey.

1 Set by standard survey procedure for the subdivision of sections.

2 Set by standard survey procedure for the subdivision of sections.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-9

DNR monument

| | | |
|---|---|---|
| 11" Maple | S37°E | 56.6 |
| 6" Poplar | N45°E | 37.0 |
| SE corner old school house | | |
| | N47°W | 76.7 |
| old fence post | | |
| | S22°W | 35.9 |

I-9

½" rerod ℄ ROAD

| | | |
|---|---|---|
| 6" W. Pine | S46°W | 45.0 |
| 6" W. Pine | S35°E | 41.4 |
| corner fence post | | |
| | S05°W | 32.0 |

1

2½' of 1¼" pipe

| | | |
|---|---|---|
| 5" W. Pine | S10°W | 39.95 |
| 18" Bl. Oak | N55°W | 35.8 |
| 8" Maple | N15°E | 6.5 |

2

2½' of 1¼" pipe

| | | |
|---|---|---|
| 12" W. Pine | S58°W | 61.1 |
| 9" Cedar | S08°W | 34.5 |

SIGNED BY Kenneth J. Ostling DATE 11-

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

STATE OF MICHIGAN KENNETH J. OSTLING LAND SURVEYOR No. 10068 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ (CHIEF OF SURVEY PARTY) DATE _____

APPROVED AND SIGNED BY _____ (MICHIGAN REGISTERED LAND SURVEYOR) DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ MONTMORENCY COUNTY

Form No. MLM736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS