(6)

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF –:	LOCATED IN –:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 15 N. S., R. 18 E. W.	J-1; J-3
2. PROPERTY CONTROLLING IN SECTION ____	,T. ____ N. S., R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ____	,T. ____ N. S., R. ____ E. W.	
4. LOT NO. ____ , RECORDED PLAT ____		
5. PRIVATE CLAIMS ____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Aug. 29, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. ~~Description of original monument and recovery and/or subsequent restoration:~~

B. (continued) Sec. 2 per original Govt. Survey.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

J-1 Fd. 3/4" pipe & accepted as N 1/4 Cor. S-2, T15N-R18N. Note: S.Barnett erroneously called this the S 1/4 Cor. of S-35, T16N-R18W, and recorded it as J-13.

J-3 Re-estab. 1/4 Cor. to Sec's. 2 & 11, equidistant & on line between Sec. Cor's to E & W. This fits U.S. (G.L.O.) distance very reasonably. Note: first attempted to restore Cor. by occupancy. Tied up most of 40 Ac. Cor's. in Sec's. 2 & 11. Just will not lead you to acceptable 1/4 Cor. position. Stover used fn. Cor. post, fn. N-E-W (we fd. 3/4" pipe) for ctr. of Sec. 11; a line across the Comp. (S.P.) S 1/4 S-11 (in lake) and Stover's (fn.Cor.) ctr. projects to rd. Ctr. to South (at approx. N 1/4 S-11) or 64'± E. of our S.P. N 1/4 Sec. 11. Just could not accept this rd.intersection as proper position for S 1/4

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (continued)

J-1			J-3		
Fd. 3/4" pipe; added DNR Mon.& Ced.Post			Set 5/8"X40" Rod w/RLS Cap. (buried)		
16" Ash	S75°E	19.3	Power Pole	S65°E	106.68
15" R. Oak	S50°W	3.0	NE'ly Cor.Conc.Dr.	S09°E	168.9
S 1/4 35 T16N-R18W	N87°53'W	26.40	Ctr. N-S Gr.Rd.	Due E	64'
N-S Rd. (old R.R. Grade)			Ctr. E-W Gr.Rd.	Due N	7'
	Due W	48'±	Set Ced.Post w/Loc.Tag		
				Due N	33'

SIGNED BY Carl F. Roser 10-2-78 DATE ____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ DATE ____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ____ DATE ____
MICHIGAN REGISTERED LAND SURVEYOR

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. ____

GOLDEN TOWNSHIP
OCEANA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET